

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CC4/LPC20007770/UEA3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 8012L

at Workshop m/s Sphuz 2amping.

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4586.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GM / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

531H

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBJ 8012L Yr Regn: 8 19

Type: M.Car / M.Cycle / Bus Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM

Make: Nissan NR350 c.c. 2400

Colour blue/white A/C: Insured / Std / NI / NA

Sp.Reading 20573 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1MC2E2620031527

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 26/6/20

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 28/7/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 2524

14/8/20 4/5 43450 confirmed with Boon Kai

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ S + RS, SI

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 18/07/2020

PLEASE ARRANGE TO SURVEY VEHICLE AT 30 BUKIT BATOK CRESCENT (S 658075)

Ng Boon Kai

CLAIM DEPARTMENT

DID : 6654_7617

FAX :

Date :

To :

LONPAC INSURANCE BHD.

ESTIMATION

Attn :

Motor Claim Department

FAX :

Email LKK: Asker

Owner :

ETHOZ Group Ltd

:

SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No :

D19MTHCVE000171

Accident Date :

26/06/2020

Vehicle No :

GBJ-8012-L

Make & Model :

NISSAN NV350 PANEL VAN 2.5 DIESEL G (A) I

ESTIMATED REPAIR COST DETAILS

Excess :

0.00

Add Excess :

0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

Nett Item

1	REAR FENDER RH	
1	REAR FENDER INNER RH	
1	TAIL LAMP PANEL RH	
1	TAIL LAMP RH	
1	END PANEL TOP GARNISH	
1	REAR BUMPER	600.10
10	REAR BUMPER CLIPS	30.00
1	REAR BUMPER SIDE RETAINER RH	
1	REAR BUMPER SIDE RETAINER LH	

3066.00	2,006.90	✓
17	1,256.20	X
17	268.20	X
17	334.80	X
17	212.50	X
17	767.80	✓
17	55.00	✓
17	48.10	✓
17	48.10	X

Date : 28/07/2020
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D19MTHCVE000171 Accident Date : 26/06/2020
Vehicle No : GBJ-8012-L Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A) 1

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR END PANEL	17 384.30	X
1	REAR MUD FLAP (R/H) 133.80	0-5 198.80	/
	Sub Total	5580.70	
	Discount 10% On Parts	(558.07)	
	<u>Special Nett Item</u>		
1	REAR FENDER ADVERTISMENT STCIKER RH	na 450.00	400
1	REAR BUMPER ADVERTSIMENT STICKER	nel 800.00	200
1	REAR WHEEL CAP RH	R 83.90	X

Date : 28/07/2020
To : LONPAC INSURANCE BHD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D19MTHCVE000171 Accident Date : 26/06/2020
Vehicle No : GBJ-8012-L Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (A) I

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1333.90	
	Labour & Misc		
	LABOUR TO FACILIATE REPAIR	1,000.00	700
	LABOUR TO SPRAY PAINT AFFECTED AREAS	800.00	500
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	40.00	20
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	80.00	x
	Sub Total	1920.00	

8,276.53

Remarks:

not Authorised

SUB TOTAL
GST 7.0 % 579.36
TOTAL 8,855.89

2281890
100
92537.01
52600.00
1-1220.00
4357.01
207
3484

Surveyor's name: neronj lllll

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 28/7/20

2/5 \$3450
4 day s.
take 1/1. 11th ago

PAGE : 3