

ASS. REC. BY:

REF:

C72/ 2000 7780/kk

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Alan's

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1320 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SE 8611 Yr Regn: C2, 14Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Traller or

Make: Lexus ES 300h c.c. 2494Colour: M. Red A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 91301 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JTHBW1GG9.02053511Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☐ S/Rim / ☒ STD A/Rim orTyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 26/7/20D.O.A. 27/7/2020

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop orFR N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/8 21 Day & 6000 Car Insur

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Factors

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06198

Vehicle Insured : GU8239H
Accident Date : 26-Jul-2020

Date : 27-Jul-2020

Our Ref : 020078 (CHINA) / CHAN

PAGE : 1

CHIN HUI CAR RENTAL
7 SIN MING IND. EST. SECTOR C
#01-76
Singapore 575642

Not Authorized
11 Day @
Resurvey After Repair

ESTIMATED COST OF REPAIR FOR LEXUS ES300H SJE86H

5 days

1 pc N/s headlamp
1 pc N/s headlamp lower bracket
1 pc Front n/s fender
1 pc N/s fender inner shield
1 pc Front bumper fascia
1 pc Front bumper reinforcement
1 pc Front bumper sponge
1 pc Front n/s bumper foglamp
1 pc N/s bumper foglamp bracket
1 pc N/s bumper foglamp chrome
1 pc Frt n/s bumper parking sensor
1 pc N/s parking sensor o ring
1 pc Front n/s bumper nozzle cover
1 pc N/s bumper nozzle arm
1 pc N/s nozzle hose joint
1 pc N/s nozzle hose

CM 2,201.30
CM 64.70
Br 1,012.10
CM 299.80
R 985.70
R 474.60
Sw 140.30
mg CM 288.40
Br 181.50
Dis 133.20
Shon 472.50
Mr 29.90
Mr 42.10
CM 564.20
Sw 32.30
Sw 64.20

6,986.80

Less 10% : 698.68

6,288.12

To rewire damaged parts and refocus
headlamp beam & reset

100%
120.00

To putty and spray replaced parts

950.00 *100%*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GU8239H

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

550/
900.00

Total : S\$ 8,258.12
=====

Singapore Dollars Eight Thousand Two Hundred
and Fifty Eight and Cents Twelve Only

Propellant:	Petrol-Electric
Max Unladen Weight:	1705 kg
Maximum Laden Weight:	2150 kg
Open Market Value:	\$45,066.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Feb 2024
Minimum PARF Benefit:	\$22,546.00
No. of Transfers:	1
IU Label No.:	1125228717
COE No.:	2013120103000533N
COE Expiry Date:	20 Feb 2024
COE Category:	B - Car (1601cc & above)
COE Registration Category:	B - Car (1601cc & above)
Quota Premium (QP) / Prevailing Quota Premium:	\$79,300.00 / -
Actual QP Paid:	\$79,300.00
QP (Regn Cat):	\$79,300.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$79,300.00
Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$25,066.00 (140%)
Actual ARF Paid:	\$45,093.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	130.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category B. This is a public service vehicle.