

ASS. REC. BY: Taughlin

REF:

CTI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / RES / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No: _____

at Workshop no: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Lim TS.

Veh No: SHC 1325XYr Regn: 2018 11 SepType: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or _____

Make: Hyundai ianigC.C. 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 246091

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HC 851 CVKU 107405Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / SR / STD A/Rim or _____Tyre Size: F: 195/65 R15R: u u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 27/7/20Survey held at Comfortdelgo by angDes. of Damages: Frt Rear / RS / NS / U/C Roof or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Report Formed: _____


Lump Sum / L.B.I. (\$ _____)

Team: ARC Repair TP(CLS0)1	JOB CARD	Sales Order:	JC NO.:305413425
Customer: COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO: SHC1325X MAKE: HYUNDAI MODEL: IONIQ(G2) YR OF MANU: 03.09.2018 CHASSIS CODE: KMHC851CVKU107405	MILEAGE FUEL E.....1/2.....F DATE/TIME IN: 27.07.2020 11:30 TARGET DATE COMPLETION DATE/TIME:	

Accident Date: 26.07.2020
Incident Nature: 3P 26.07.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:	SERVICE ADVISOR	CUSTOMER'S SIGNATURE
Exit Pass	Vehicle No.: SHC1325X	
Signature	LIMITS	