T 0720 / SHC1325X /WT/CK(st)

Your Ref:

Dear Sir

Date

11-Aug-2020

CDGE Taxi Claims Dept 59 Loyang Drive 4th Flr

Singapore 508969

CHINA TAIPING INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn: Motor Claims Department

WITHOUT PREJUDICE

COMFORTDELGRO ENGINEERING

> ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> > Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > > www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell addell Road

205 Braddell Road Singapore 579701

> **Loyang** 59 Loyang Drive

Singapore 508969
Sin Ming
383 Sin Ming Drive

Singapore 575717
Pandan

45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

ACCIDENT INVOLVING OUR TAXI SHC1325X YOUR INSURED SLK2986S
AND OTHER ON 26-Jul-2020

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No:

SHC1325X which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : **SLK2986S** we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	1,190.82
6	2 days Loss of Rental @ \$ 128.40 per day	\$	256.80
3	Survey Report Fees (Surveyed by M/s LKK)	\$	<u>=</u>
3	The state of the s	\$	7.49
4	LTA Search Fees	Ψ	
5	GIA / Police Report Fees	\$_	-
10 -0		\$	-
6	Towing Fees Sub Total:	\$	1,455.11

HIRER'S CLAIM

We enclose herewith the following documents to support the claims: -

a) Original repair bill:

b) LTA search slip/s of:

SLK2986S

c) GIA / Police report/s of :

SHC1325X

d) Letter of authority from owner / hirer / operator

() Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance

() PIR (x) Rental Rate letter

(x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Catherine Koh

CDGE Claims Department

Tel: 6214 8733 Fax: 6214 1843 Email: catherinekoh@cdge.com.sg

This is a computer generated letter. No signature is required.



A member of

reget .

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

Hyundai Ioniq SHC1325X , SLK2986S

ON 26-Jul-20 11:40

ALONG

UE SQUARE TAXI STAND

I / We

TANG CHEE LOK

(Hirer) NRIC No.:

SXXXX069D

and/or

(Relief) NRIC No.: SXXXX069D

Taxi Number

SHC1325X

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

27-Jul-2020

Name of Hirer

TANG CHEE LOK

Hirer NRIC

SXXXX069D

Signature:

Address

504 ANG MO KIO AVENUE 8 #09-2...

560504

Contact No.

97121855



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 7687 320 Ubi Road 3 Singapore 408649

COMPANY REG. NO.: 199506048W Page: 1

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHC1325X

INV. NO/DATE 91517408 30.07.2020

MAKE HYUNDAI

JOB NO. 305413425

MODEL IONIQ(G2)

ODOMETER READING

DATE OF REG 03.09.2018

DATE/TIME IN 27.07.2020 11:30

CHARGE CODE

Descr	ription: 3P 26.07	. 2020	KMHC851	CVKU107405		
S/No	Part No.		Qty	Unit Price	%Disc	Net
PART	REQUISITION					
0001	04-01-0104-2533	REAR BUMPER CENTRE-Black	1	451.25	20.00	361.00
0002	04-01-0104-2544	REAR BUMPER TOW COVER	1	5.40	20.00	4.32
0003	09-01-9999-0068	REVERSE SENSOR	1	180.00	0.00	180.00
0004	04-01-0101-0111	REAR BUMPER CLIPS	10	2.20	20.00	17.60
			SUB-TOTAL	:		562.92
JOB NATURE						
0001	PB	PANEL BEATING		320.00		320.00
0002	SP	SPRAYPAINT CHARGE		200.00		200.00
0003	L	R/I REVERSE SENSOR		30.00		30.00
	2 1		SUB-TOTAL	:		550.00

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

A	CCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
	8010012	91517408	1,190.82	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

S9 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649 24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 7687

COMPANY REG. NO.: 199506048W

Page: 2

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHC1325X

INV. NO/DATE 91517408 30.07.2020

MAKE HYUNDAI

JOB NO. 305413425

MODEL IONIQ(G2) ODOMETER READING

DATE OF REG 03.09.2018

DATE/TIME IN 27.07.2020 11:30

CHASSIS CODE KMHC851CVKU107405

Items total

1,112.92

Add GST @

7.000 %

77.90

Invoice amount

1,190.82

Issued by : KATHERINETAN 03.08.2020 15:14:21 Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

INVOICE No. **AMOUNT** BANK/CHQ No ACCOUNT No. 1,190.82 8010012 91517408

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT20070346

Date: 03 August 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

26/07/2020 @ 11:40 hrs

ALONG

UE SQUARE TAXI STAND

INVOLVING

SLK2986S

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC1325X (the "Taxi"). The Taxi was hired to TANG CHEE LOK IC NO SXXXX069D a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$128.40 per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	HOURS OPERATED (TIME)	FROM TO	6.12 Hm 9.13 pm	638 Hm 9/31 Pm	6-21 Pm 1130	747								
	MILEAGE TRAVELLED (KM)		1403	332	F	8				\(
	MILEAGE READING		245636	245969		27					,			
	NAME OF DRIVER	חשויום וט שוייהיי			Accident	Repair							3	
	DATE	2	25/1/2020	26/7 /2020	27/7/2020	505 Am 1016Fm 28 17/2020	5-21 Hm 1056pm 29 17/2020	30/7/2020						
µ2007079	SATED (TIME	2		9.MPm	1000/m	10-16Fm	1056Bn	1026Pm	936Pm	10.038m	Mozer	JEG. B.	AL201	
	HOURS OPERATED (TIME	FROM	511 Am 1021 Ph	5-13 Am 9-14Pm	5:554m 1000/h	FOT AM	5.21 Am	6.38 Am 1026Pm	524 Am 936 Bi	5:35 Am 10,638m	627 Am Walton	526 Han 751 h.	533 Am 1027 PM	
	MILEAGE	(KM)	224	350	336	438	434	34	342	326	412	351	403	

i,

Enquire Vehicle Insurance Details

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SLK2986S 26 Jul 2020 / 11:40:00 Successful

C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous OK

SHCBUSX