

CS3/III19016240/Gtf3-1

21/03/2002

ASS. REC. BY:

REF:

~~CS3/III19016240/Gtf3-1~~

Special Instruction:

Surveyor:

Carine Kek

ASSIGNMENT (Office)

28/07/2020

From (Person):

~~Subash Kumar~~

of

TH

Date/Time:

~~13.9.19 1.44p.m~~

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBC 1930V

Insured:

SHA 2603Y

at Workshop m/s

Alai motor

Tel:

9437 5035

of

Blk 1 Kaki Bukit hse 6 - 02-65 Alibay

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9.7.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

13.9.19

2.44p.m

Person Contacted:

Ah Lai

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBC 1930V - X

SHA 2603Y - CC3 / TH 19009157 / kgas

DOA - 22/05/2019

Surveyor:

PRS
Bel.

REF:

IV

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Alai Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PRC 19304Yr Regn: Dec / 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB600FA

c.c

599Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZDCPC41C 07F020341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70ZR17R: 180/55-17 CTMSUN

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 4 mmL/Bal. 4 mmL/Bal. 4 mm

D.O.A. _____

D.O.I. 13-09-19Survey held at w/sDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or 3pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 8000 - \$ 10K

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 120

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

S + RS, SI



Interview (\$ _____)

Photos



Tech. Invs (\$ _____)

Others



Weekend (\$ _____)

)

TOTAL

Report Format: PRS

Lump Sum / I.B.I.: (\$ _____)

11

131

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) Edit Reg		25 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	-		
Vehicle Reg. No.:	FBC1930U	Date of Loss:	09/07/2019 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHA2603Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Alai Motor (HQ) 2 KAKI BUKIT AVE 6 #02-65, 417883 Kaki Bukit - Tel: 94375035		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 13 September 2019 1:24 PM
To: Sally; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: ACCIDENT ON 09/07/2019 INVOLVING SHA2603Y (III) & FBC1930U
Attachments: list of surveyor.pdf; sha2603y_20190913100722.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : FBC1930U
III INSURED VEHICLE NO. : SHA2603Y
DATE OF LOSS : 09.07.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANT to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.
Surveyor kindly upload this assignment to Merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Sally [mailto:info@catherinelimllc.com]
Sent: 13 September, 2019 10:46 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: ACCIDENT ON 09/07/2019 INVOLVING SHA2603Y (III) & FBC1930U

Dear Sir (Without Prejudice)

We refer to your email.

Our client is not agreeable to your list of surveyor and attached herewith our client's list of surveyor as single joint.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
Sent: Friday, September 13, 2019 10:14 AM
To: Catherine Lim LLC
Subject: ACCIDENT ON 09/07/2019 INVOLVING SHA2603Y (III) & FBC1930U

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- VP Appraisal
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including

the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
 翠 NOTARY PUBLIC - 公证官
 玲 COMMISSIONER FOR OATHS - 宣誓官
 律
 師 CATHERINE C.L.LIM
 館 DIRECTOR
 LL.B (HONS) SINGAPORE - 法律系 - 律師
 M.B.A. (BUSINESS LAW) - 商業系 - 碩士

20 Havelock Road #03-01
 Central Square Singapore 059765
 UEN No. 201310922K
 GST Registration No. 201310922K
 Tel: (65) 6438 5500
 Fax: (65) 6438 0111
 www.catherinelimllc.com
 Email: info@catherinelimllc.com
 CATHERINE LIM LLC is a law corporation
 with limited liability



Your Ref: SHA 2603Y
 Our Ref: CL/190929/T/MCS.sg

12 September 2019

India International Insurance Pte Ltd
 64 Cecil Street #04-05
 IOB Building
 Singapore 049711
 Attn: Motor Claims Dept

via fax: 6224 4174 & by hand

Comfort Transportation Pte Ltd
 383 Sin Ming Drive
 GAS Building
 Singapore 575717

CERTIFICATE OF POSTING
 (Please be informed that all supporting documents
 have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
 PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

ACCIDENT INVOLVING FBC 1930U / SHA 2603Y ON 9.7.2019 ALONG INTERNATIONAL ROAD

We are instructed by ZULKIFLEE BIN ZAINAL to notify you of a road traffic accident involving our client's vehicle No. FBC 1930U and vehicle No. SHA 2603Y driven by you at the material time. A copy of the Singapore Accident Statement and or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Alai Motor Centre
 Blk 1 Kaki Bukit Ave 6
 #02-65 Autobay Kaki Bukit

Contact: 9437 5035 (Alai)

Yours faithfully


 cc: clients

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:		Singapore NRIC
Owner ID:		185B
Vehicle Details		
Vehicle No.:		FBC1930U
Vehicle to be Exported:		No
Intended Deregistration Date:		30 Sep 2019
Vehicle Make:		HONDA
Vehicle Model:		CB600FA-PC41
Primary Colour:		Blue
Manufacturing Year:		2007
Engine No.:		PC41E2021044
Chassis No.:		ZDCPC41C07F020341
Maximum Power Output:		-
Open Market Value:		\$11,307.00
Original Registration Date:		10 Dec 2007
First Registration Date:		10 Dec 2007
Transfer Count:		6
Actual ARF Paid:		\$1,697.00
Intended PARF Rebate Details		
PARF Eligibility:		No
PARF Eligibility Expiry Date:		-
PARF Rebate Amount:		\$0.00
Intended COE Rebate Details		
COE Expiry Date:		09 Dec 2027
COE Category:		D - Motorcycle
COE Period(Years):		10
PQP Paid:		\$5,385.00
COE Rebate Amount:		\$4,410.00
Total Rebate Amount:		\$4,410.00

The information contained herein is correct as at 30 Sep 2019

OK



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190803/7025

1 of 3

Report No. T/20190803/7025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/08/2019 22:06		Vide Report No.:		Station Diary No.:	
Name of Informant: ZULKIFLEE BIN ZAINAL		Address: APT BLK 940 JURONG WEST STREET 91 #11-447 SINGAPORE 640940			
ID Type / ID No.: NRIC NO / S6807185B		Contact No.:		Mobile: 90408483	
Nationality: SINGAPORE CITIZEN		Email: zulkiflee14@gmail.com			
Sex: Male	Age: 51	Date of Birth: 14/03/1968	Type of Informant: Rider		
Race: Malay		Language: English		Institution / School Name:	
Occupation: Lorry driver		Driving Licence Information: Class: 2,3,4,5		Date of Expiry:	

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/07/2019 18:45	Type of Location: X-Junction
Location: INTERNATIONAL ROAD				
Weather: Drizzling		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

FBC1930U	Motorcycle	HONDA	CB600FA-PC41	Blue	0
	Unconscious				0

FBC1930U	NTUC Income Insurance Co-Operative Limited	5096234324-01	10/12/2018	09/12/2019
----------	--	---------------	------------	------------



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190803/7025

2 of 3

Report No. T/20190803/7025

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	ZULKIFLEE BIN ZAINAL	ID No.	S6807185B
Related Vehicle	FBC1930U (Motorcycle)	Contact No.	90408483
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2,3,4,5 Date of Expiry: NIL
Date Treatment	09/07/2019	Date Discharge	26/07/2019
No. of Days granted Medical Leave	20	Degree of Injury	Serious
Name	Unknown Driver	ID No.	NIL
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was riding along Pioneer Road North toward AYE. At junction International Road the traffic light was green. I moved ahead but one motor car from opposite direction coming towards me. I was unconscious and i woke up in ambulance. I do know who hit me. I was warded 18 days and broke both hands and left leg. I was discharged 26 July 19. I am now wheelchair bound and cannot make report.

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190803/7025

3 of 3

Report No. T/20190803/7025

CONTINUATION OF REPORTSketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
MA JUNXIANG
Contact No.: 65476251

Authentication Stamp
NP163

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
03/08/2019 22:06

Classification Of Case:



T/20190820/2050

1 of 3

Report No. T/20190820/2050

Case Summary Form (CSF For NP168)

Manual NP168 Form Serial No T/20190803/7025
Report Number T/20190820/2050
Vide Report Number T/20190803/7025
Date/Time of Report Made 20/08/2019 12:22
Place Report Lodged Traffic Police
Type of Informant Rider
Name of Informant zulkiflee bin zainal
ID Type / ID No. NRIC NO / S6807185B
Home/Office
Mobile 90408483
Email
Type of Accident Injury / Attended by Police
Drink Drive No
Anyone conveyed by ambulance No
Date/Time of Accident 09/07/2019 06:45
Accident Location INTERNATIONAL ROAD

FBC1930U	Motorcycle	HONDA	CB600FA-PC41	Blue	0
Any Pedestrian Involved: No					
No. of Pedestrians Injured: NIL					
Use of Pedestrian Crossing: NA					



T/20190820/2050

3 of 3

Report No. T/20190820/2050

Continuation of CSF For NP168Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Case Sensitivity

No

Officer-In-Charge of Case

TP / GIT /
THABAGESH JEYATHESH

Classification of Case

1) INJURY / ATTENDED BY POLICE

SINGAPORE
POLICE FORCE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2019 10:12 Edit Reg		13 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: -									
Vehicle Reg. No.: FBC1930U		Date of Loss: 09/07/2019 00:00 - :59 [138 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHA2603Y		Policy No. (Claimant):							
		Excess:							
Repairer: Alai Motor (HQ) 2 KAKI BUKIT AVE 6 #02-65, 417883 Kaki Bukit - Tel: 94375035									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBC1930U
[SHA2603Y]

TP

-

Jul 9 2019 12:00AM

[-]

Alai Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 18:45	General View	 Load JPG	☒
2	25/09/19 18:45	General View	 Load JPG	☒
3	25/09/19 18:45	General View	 Load JPG	☒
4	25/09/19 18:45	General View	 Load JPG	☒
5	25/09/19 18:45	General View	 Load JPG	☒
6	25/09/19 18:45	General View	 Load JPG	☒
7	25/09/19 18:45	General View	 Load JPG	☒
8	25/09/19 18:45	General View	 Load JPG	☒
9	25/09/19 18:45	General View	 Load JPG	☒
10	25/09/19 18:45	General View	 Load JPG	☒
11	25/09/19 18:45	General View	 Load JPG	☒
12	25/09/19 18:45	General View	 Load JPG	☒
13	25/09/19 18:45	General View	 Load JPG	☒
14	25/09/19 18:45	General View	 Load JPG	☒
15	25/09/19 18:45	General View	 Load JPG	☒
16	25/09/19 18:45	General View	 Load JPG	☒
17	25/09/19 18:45	General View	 Load JPG	☒
18	25/09/19 18:45	General View	 Load JPG	☒
19	25/09/19 18:45	General View	 Load JPG	☒
20	25/09/19 18:45	General View	 Load JPG	☒
21	25/09/19 18:45	General View	 Load JPG	☒
22	25/09/19 18:45	General View	 Load JPG	☒
23	25/09/19 18:45	General View	 Load JPG	☒
24	25/09/19 18:45	General View	 Load JPG	☒
25	25/09/19 18:45	General View	 Load JPG	☒
26	25/09/19 18:45	General View	 Load JPG	☒
27	25/09/19 18:45	General View	 Load JPG	☒
28	25/09/19 18:45	General View	 Load JPG	☒
29	25/09/19 18:45	General View	 Load JPG	☒
30	25/09/19 18:45	General View	 Load JPG	☒
31	25/09/19 18:45	General View	 Load JPG	☒
32	25/09/19 18:45	General View	 Load JPG	☒
33	25/09/19 18:45	General View	 Load JPG	☒
34	25/09/19 18:45	General View	 Load JPG	☒
35	25/09/19 18:45	General View	 Load JPG	☒
36	25/09/19 18:45	General View	 Load JPG	☒
37	25/09/19 18:45	General View	 Load JPG	☒
38	25/09/19 18:45	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/09/19 08:49	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19016240/GCF3E2

Date: 07/10/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant
Vehicle No : FBC1930U
Insured Vehicle No : SHA2603Y

Date of Loss: 09/07/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBC1930U**

Make & Model: HONDA CB600FA-PC41, 599cc

Engine No: PC41E2021044

Reg. Date: 10/12/2007 (Man. Year: 2007)

Chassis No: ZDCPC41C07F020341

Colour: Red

Odometer: 0 km

Engine Capacity: 599 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17

Rear Tyre Size: 180/55-17

Front Left Side: Pirelli 4 mm

Rear Left Side: Timsun 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/09/2019

Date Inspected: 13/09/2019 Inspected At:

 Alai Motor (HQ)
 1 KAKI BUKIT AVENUE 6
 #02-65 AUTOBAY @ KAKI BUKIT
 SINGAPORE 417883

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Oct 2019)

Parts: N/A HONDA CB600FA-PC41 599cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBC1930U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >