



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20007806/Ksf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 14-08-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 2873Y	Veh. Inspected	GBJ 8063P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002216/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	29/07/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200 (A)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VSKYBAM20Z0178799	Colour	GREY
Odometer	53466	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	GOODYEAR	2 mm
L/H Front Tyre	175/70 R14	GOODYEAR	2 mm
R/H Rear Tyre	175/70 R14	GOODYEAR	2 mm
L/H Rear Tyre	175/70 R14	GOODYEAR	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/07/2020	Inspection Date	29/07/2020
Survey held at	60 Jalan Lam Huat #03-35/36 singapore 737869		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------