

ASS. REC. BY:

REF:

CC4/FCI 20007807

da3

0574

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR 3961Tat Workshop m/s VOLKSWAGENof 247, ALEXANDRA RDInsured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 106k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJR 3961TYr Regn: 2020 / JulyType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: VOLKSWAGEN GOLF 1.4 TSI c.c. 1395Colour: RED A/C: Insured / Std / NI / NASp. Reading: 256 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW222AUZKW213052Gen. Cond: Good ☒ Fair / Poor / BurntSteering: In order ☒ Jammed / Leaked / Burnt or _____Brake: In order ☒ Jammed / Leaked / Burnt or _____Modi: Nil ☒ S/Rim / STD A/Rim or _____

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 25/07/2020D.O.I. 30/07/2020Survey held at VOLKSWAGENDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

☐ : Final Report

Transportation: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / L.S. (\$ _____)

x Used 2020 Volkswagen Golf 1.4A x

Merimen e-Claims x +

gcar mart.com/used_cars/info.php?ID=905606&DL=3103

Volkswagen Golf 1.4A TSI Comfortline

Overview

Financial

Accessories

Similar

Research

Photos

Map

Das WeltAuto.

Used cars you can trust. Guaranteed.

Price \$101,988

Depreciation  \$9,620 /yr
View models with similar depre

Reg Date 24-Feb-2020
(9yrs 6mths 24days COE left)

Mileage 7,500 km

Manufactured  2019

Road Tax  \$624 /yr

Transmission Auto

Dereg Value  \$40,116 as of today (change)

OMV  \$19,703

COE  \$40,889

ARF  \$19,703

Engine Cap 1,395 cc

Power 92.0 kW (123 bhp)

Curb Weight  1,270 kg

No. of Owners 1

Type of Vehicle Hatchback

Features

123Bhp Turbocharger TSI Engine, 200Nm Torque, 7 Speed DSG Gearbox, 0-100km/h In 9.9 Sec. Bluemotion Technology, CD Player, SD Card, Auto Headlights. View specs of the Volkswagen Golf (2012)

STORY

Location

Short

No