

ASS. REC. BY:

REF: CS/CTI20007823/Usf3

Special Instruction:

Surveyor: MARCUS ASSIGNMENT (Office)

From (Person): Pauline Tham of CTI Date/Time: 29/7/2020 1:53 PM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGN 5973C Insured: GBD 9341L

at Workshop m/s Tan Lim Motor Pte Ltd Tel: 6858 5151

of 1 Defu Lane 6

Policy No: \_\_\_\_\_ Claim No: SNM20D202638

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 29.07.2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 29-7-20 2.48P.M Person Contacted: CAYMEN Vehicle  IN  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SGN 5973C- <input checked="" type="checkbox"/>
	GBD 9341L- <input checked="" type="checkbox"/>