



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN : JOHHNY YONG			Ref: CS3/ASM19005366/Gqf3e2-1 Date: 08/02/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SJN 2199E	Veh. Inspected	SGU 2306L	
Policy No.	GA391476/1	Coverage (\$)	0.00	
Claim No.	S9M01HP6	Excess (\$)	0.00	
Assign From	JOHHNY YONG	Assign Date	29/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	FD11101620	Colour	SILVER	
Odometer	462201 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	5 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	5 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	14/09/2018	Inspection Date	22/01/2021	
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	