

REF: CS3 / Asm 19005366 / Gqf3-1

Special Instruction:

From (Person): Johnny Yang of Asm Date/Time: 29-7-2020
Estimated Cost: _____ Bill to: _____

4/sum: ~~\$11,700.00~~ 3500

Third Parties:

Claimant:

Surveyor: MC-COY APPRAISER

Workshop: SHENG LI LAI

OD (TP Re-inspection) / Evaluation

To Inspect Vehicle No: SGU 2306 L

Insured: SJN 2199E

at Workshop m/s Shung Li Lai

Tel: 62271272

of MO2 Kaki Bukit Ave 2 #01-36

Policy No:

Claim No: 59m01HP6

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.9.2018

(Client's Record)

Inspection: 5-AUG-2020 3p.m

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 12 days)
Date/Time: 04/02/21 Submit Final Fig _____, _____ days (Red \$ _____ / _____ %; Original _____ days)

Date/Time: 04/02/21 Submit Final Pg LS \$1400, 4 days (Red \$ 2100 / 60 %; Original 4 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

Para(3) : Nett Value

Market Value : _____

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 04/02/21 File Pass to Typist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____