



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20007828/Ags3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 18-09-2020



ATTN: PETER WANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBB 1919J	Veh. Inspected	SLX 464B
Policy No.	VA1/GA180039	Coverage (\$)	0.00
Claim No.	S0M02RDZ	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	29/07/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GK81200033	Colour	BLACK
Odometer	127140	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	PIRELLI	6 mm
L/H Front Tyre	185/60 R15	PIRELLI	6 mm
R/H Rear Tyre	185/60 R15	PIRELLI	6 mm
L/H Rear Tyre	185/60 R15	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/07/2020	Inspection Date	29/07/2020
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------