

ASSIGNMENT

02 July 2024

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal: or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 3288 B Yr Regn: July 2016Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685Colour Blue A/C: Insured / Std / NI / NASp. Reading 413123 T/Radio: Insured / Std / NI / NAEng/No: D4FDGU655912C/No: KMHLB4HUMGU091881Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R 16R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

 Hankook

Front

Rear

R/Bal. S mmR/Bal. S mmL/Bal. S mmL/Bal. S mmD.O.A. 25/07/2020D.O.A. 29/07/2020Survey held at Bifrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

EQ GBG 3548 G

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)