

This  
**REPORT**

has been awarded to

Vehicle No: IMPORT USED CAR  
Make & Model: PORSCHE MACAN 2.0  
Date: 30/7/2020

**For the Evaluation (Full)**

by

**The Used Car Evaluation Specialist**

OVERALL GRADING			
☆☆☆☆	☆☆☆	☆☆	☆
A			

- Note: 1. This Evaluation does not include all the required Tests for the LTA Road Worthiness Inspection which is also available LTA Vehicle Inspection package, please check with our friendly STA Evaluation staff.
2. This is NOT a LTA Road Worthiness Inspection Certificate and NOT valid for Road Tax Renewal.

## EVALUATION REPORT

### Vehicle Details

Vehicle Number: IMPORT USED  
Engine Number: DLH027259  
(Extracted from OneMotoring)  
IU Number: NA  
Inspection Due Date: \_\_\_\_\_

Chassis Number: WP1ZZZ95ZKLB08651  
(Extracted from OneMotoring)  
Mileage (Before Evaluation): 3398 KM  
Registration Date: 1 Jun 2019

Photo - Front View



Photo - Rear View



Photo - Chassis Number



Photo - Dashboard (Ignition Only)



Photo - Engine Bay View




Photo - Dashboard Engine Running





## EVALUATION REPORT

### 5 Fluid Level

Engine oil	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Power Steering oil	<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input checked="" type="checkbox"/> NA
Transmission oil	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Brake fluid	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Clutch oil	<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input checked="" type="checkbox"/> NA
Coolant	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

### 6 Boot

Electric tailgate	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Battery	<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input checked="" type="checkbox"/> NA
Weather seal	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Rear sills & Spot welds	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Sealant & silicon	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Spare Tyres & Spare Tyres repair kit	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Tools & kit	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

### 7 Bodyworks

Front windscreen	82 %	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Front windows	77 %	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Rear windows	22 %	<input type="checkbox"/> Pass	<input checked="" type="checkbox"/> Fail	<input type="checkbox"/> NA
Rear windscreen	30 %	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Bonnet		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Bumper		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Fenders		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Doors		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Roof		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Boot		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Head Tail lights assembly		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Number plate		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Front OPC seal	ROV	<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input checked="" type="checkbox"/> NA
Rear OPC seal	ROV	<input type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input checked="" type="checkbox"/> NA
Door side sill & Spot welds		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Weather Seal		<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

### 8 Interior

Horn	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Headlights Tailights	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Signal lights	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Hazard lights	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Warning light error message	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Washer wiper	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Electrical wing mirrors	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Functionality Power windows	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Aircon	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Parking Brake	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Functionality Doors	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Seats Adjust	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA
Seats belts buckle	<input checked="" type="checkbox"/> Pass	<input type="checkbox"/> Fail	<input type="checkbox"/> NA

### Summary Report

Form T-STAI-WI-EVAL-001-02 Rev 00


## EVALUATION REPORT

### Battery Testing

Vehicle number IMPORT USED CAR

Date created 30/7/2020

### Photo - Battery Test



- 7 Without limiting the generality of the above and subject to clause 8 below, STA's AGGREGATE LIABILITY TO YOU (IF ANY), IN CONTRACT OR TORT OR UNDER STATUTE OR AT LAW OR OTHERWISE, FOR ANY LOSS OR DAMAGE SUFFERED BY YOU (OR BY ANY OTHER PARTY) ARISING FROM OR IN CONNECTION WITH THE EVALUATION/ASSESSMENT SERVICES, HOWEVER THE LOSS OR DAMAGE IS CAUSED, INCLUDING OUR NEGLIGENCE, SHALL BE LIMITED TO 10X THE EVALUATION FEES PAID BY YOU. HOWEVER THIS LIABILITY DOES NOT IN ANYWAY EXTEND COVER WEAR AND TEAR ITEMS FOR WHICH NO LIABILITY EXISTS.
- 8 If you are unsatisfied with the certificate/assessment report and felt you have suffered loss or damage and have a valid claim, you shall notify STA immediately when the claim arises and the motor vehicle must (unless otherwise agreed by STA) be brought back to STA for verification of your claim by the next working day. STA shall have the right (but not the obligation) to have the vehicle serviced/repared to the condition certified in the assessment report if it determines in its sole discretion that there is a manifest error in the certificate/assessment report issued. Upon completion of service/repair, no other claim shall be made by the customer or any other party relating to the evaluation/assessment services rendered or the assessment report/certificate issued.
- 9 Vehicle parked overnight at our premises will be at customers owners own risk. STA are not liable to you or any person with you for damage to, destruction of, theft of or delivery up of any property (including anything in or on your vehicle or any other vehicle); however caused, and you release and indemnify us from any claim which you might otherwise have against us. We will not be liable to you for delivery of your vehicle to any person who did not have authority to take your vehicle and even if the person taking the vehicle does not have your authority.

I, the under-mentioned customer, unconditionally agree to the foregoing terms and conditions and hereby request that an evaluation of my motor vehicle be conducted.

Time in	<u>30/7/2020 11:02:58 am</u>	Time out (Printed)	<u>30/7/2020 3:33:57 pm</u>
Signature	_____		
Name	<u>Ck</u>	Tel	<u>9729 7000</u>
NRIC	_____	Mileage after	<u>3398</u> KM
Company	<u>Global Carz Pte Ltd</u>		
Address	<u>159 Sin Ming Road #01-03 Amtech Building Singapore 575625</u>		

Date created 30/7/2020





# Car-O-Liner Vision2 X3


## Lower body Repair Report

1.27.19324.1 t:0  
2020-07-30

**Customer**  
Name GLOBAL CARZ  
Address  
City  
State  
E-mail  
Zip  
Phone  
Insurance  
Claim No  
Phone  
Insurance Co  
Adjuster  
E-mail

**Vehicle**  
DataSheet 17:043  
Make Porsche  
Model Macan  
Year 2014-  
License No MACAN 2.0  
Issue 2020-01-01  
Type 5D/4WD  
VIN  
Miles  
Job  
Start Date 2020-07-30  
End Date 2020-07-30

Workorder 2020-07-30-11  
Technician HAKKIM  
Sign



### BodyShop

Company STA Inspection Centre  
Address 13 KAKI BUKIT ROAD 4, #01-02  
City SINGAPORE Zip 417807  
State Phone 63840606  
E-mail information@stai.com.sg

### Notes

WITH IN ACCEPTABLE TOLERANCE



# TAX INVOICE

Global Carz Pte Ltd  
No.58 Defu Lane 1, Trans Cab Building, Singapore 539498.  
539498

Invoice Date  
30 Jul 2020

Invoice Number  
INV-0017063

Reference  
IMPORT USED CAR

Complete Evaluation  
201500060W

Complete Evaluation Pte  
Ltd  
c/o STA Evaluation  
13 Kaki Bukit Road 4,  
#01-02, Bartley Biz Centre  
SINGAPORE 417807  
Phone: 6264 0606

Description	Quantity	Unit Price	Tax	Amount SGD
Evaluation Package A - KB	1.00	175.70	7%	175.70
Subtotal				175.70
TOTAL LOCAL SUPPLY OF GOODS AND SERVICES 7%				12.30
TOTAL SGD				188.00
Less Amount Paid				188.00
AMOUNT DUE SGD				0.00

Due Date: 30 Jul 2020  
Cheque payable to "Complete Evaluation Pte Ltd"

## PAYMENT ADVICE

To: Complete Evaluation Pte Ltd  
c/o STA Evaluation  
13 Kaki Bukit Road 4, #01-02, Bartley Biz Centre  
SINGAPORE 417807  
Phone: 6264 0606

Customer Global Carz Pte Ltd

Invoice Number INV-0017063

Amount Due 0.00

Due Date 30 Jul 2020

Amount Enclosed

Enter the amount you are paying above