

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

29 JUL 2020

ESTIMATE

Estimate No. : b1 55637
Date Estimated : 29/07/2020
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Chan Wah Hak Nien Shen
12 Lucky Crescent

singapore 467734

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1132P	WBAHS120005J97008	28/06/2017	X1 sDrive18i	0

DESCRIPTION

To replace rear boot lid, rear bumper include remove attachment etc

Spray painting rear boot lid and rear bumper

To replace rear windscreen glass.

To supply and install rear windscreen solar film.

To conduct water leak tests.

To carry out body cavity preservation.
(Per panel).

To remove and install boot compartment carpet and garnish to facilitate repairs.

To check electrical wiring systems and lightings at the rear section for proper function.

To supply rear emboss number plate.

To replace rear exhaust silencer including alignment system and conduct checks for leak.

Sundries

VALUE

~~1700~~ 2,550.00

~~1730~~ 1,923.00

~~574~~ 676.00

Xm ? 625.00

~~75.00~~

~~100~~ 118.00

~~230~~ 271.00

~~150~~ 177.00

17 X 83.00

Xm 451? 531.00

80/? 150.00

Total Labour 1: 7,179.00

DESCRIPTION	QTY	PRIC	VALUE
SILENCER CLAMPING BUSH ? x suc	1	54.60	54.60
RUBBER MOUNTING ? x suc	2	17.70	35.40
REAR SILENCER ? x suc	1	1,178.35	1,178.35
TAILPIPE TRIM BLACK CHROME ? x suc	1	112.20	112.20
BOOTLID 54	1	1,236.65	1,236.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55637
Date Estimated : 29/07/2020
Prepared By : Chua Kee Sin

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1132P	WBAHS120005J97008	28/06/2017	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID LH HINGE <i>Xnn</i>	1	79.75	79.75
BOOTLID RH HINGE <i>Xnn</i>	1	79.75	79.75
RR BUMPER CARRIER <i>? xsv</i>	1	496.35	496.35
MOUNTING SMART OPENER <i>? xsv</i>	1	45.55	45.55
REAR TRIM UNDERRIDE PROTECTION (X1) <i>de</i>	1	190.80	190.80
RR BUMPER LH CORNER MOUNTING <i>? xsv</i>	1	142.65	142.65
RR BUMPER RH CORNER MOUNTING <i>? xsv</i>	1	142.65	142.65
Abrasion gua <i>? xnn</i>	1	2.55	2.55
Abrasion gua <i>? xnn</i>	1	2.55	2.55
REAR BUMPER PANEL PRIMED <i>repair</i>	1	903.40	903.40
REAR BUMPER MIDDLE TRIM PANEL (PDC) <i>de</i>	1	265.65	265.65
REAR BUMPER TRIM BOTTOM (LINES) <i>cut</i>	1	232.45	232.45
EMBLEM GROMMET <i>neu</i>	2	0.85	1.70
BMW PLAQUE WITH ADHESIVE FILM <i>neu</i>	1	71.60	71.60
LETTERING X1 <i>neu</i>	1	64.45	64.45
STRIKER BOOT LID <i>? xsv</i>	1	59.80	59.80
LOCK TRUNK LID <i>? xsv</i>	1	229.10	229.10
SOFT CLOSE AUTOMATIC <i>? xsv</i>	1	612.10	612.10
BOOT LID/TAILOATE PUSH BOTTON ICAM <i>? xsv</i>	1	48.65	48.65
Lock plate <i>? xsv</i>	1	12.40	12.40
BUMP STOP <i>neu</i> NN	10	3.75	37.50
REAR BUMPER TOWING EYE COVER <i>xsv</i>	1	36.80	36.80
REAR WINDOW (ESG) <i>? photo? xnn</i>	1	851.00	851.00
HOOK AND LOOP FASTENER <i>? xnn</i>	4	2.85	11.40
HOOK AND LOOP FASTENER <i>? xnn</i>	4	2.85	11.40
CLAMP <i>? xnn</i>	4	2.39	9.56
AEROBLADE (SCHWARZ) <i>? xnn</i>	1	393.50	393.50
BOOTLID SEALING <i>neu xnn</i>	1	166.50	166.50
CLIP <i>neu xnn</i>	26	1.20	31.20
EXPANDING RIVET BLACK <i>neu</i>	26/0	1.40	36.40
REAR LH REFLECTOR <i>? xsv</i>	1	38.85	38.85
ULTRASONIC SENSOR BLACK <i>? xsv</i>	4	249.95	999.80
DECOUPING RING PDC TORQUE CONVERTER <i>? xnn</i>	4	5.10	20.40
(DG) CLEANER R1 (100ML) <i>neu</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>neu</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) <i>neu</i>	1	27.85	27.85

Total Parts : 9,262.51

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55637
Date Estimated : 29/07/2020
Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1132P	WBAHS120005J97008	28/06/2017	X1 sDrive18i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 17/08/2020 @ 1349 Excess S\$ _____

Surveyor's Name Rahul Sign _____

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 5 days



Labour 1	:	7,179.00
Parts	:	9,262.51
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,150.91
Grand Total	:	17,592.42

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **