

ASS. REC. BY: Pam

REF:

CS/CT120007856/R19/13

38B

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____


OD (TP) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLQ1132Pat Workshop m/s PERFORMANCEof 307, ALUMINUM ROInsured: CTIPolicy No. DMCVSN30612119000Claims No. SNM20D202645C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 98K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ1132P Yr Regn: 2017 / JunType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W X1 50RIVE 181 AT c.c 1499Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 20800 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAH5120005 J97008Gen. Cond: Good / Fair / Poor / BurntSteering: (Order) / Jammed / Leaked / Burnt orBrake: (Order) / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50R18R: 74BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 29/07/2020 D.O.I. 17/08/2020Survey held at PERFORMANCEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/08/20@2.38pm	revised to Adeline Chng via Merimen.
10/09/20@2.28pm	Rasul finalised with Mohamad final fig \$7048.70, 5 days (Red \$9408.11, 57%)

Date/Time, File Pass to?

☐ : Preli. Report

11/10/09 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Report Format: MER-TPLump Sum / L.B.A. fig: 7048.70

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Due 7/8
17/8/2020
any & repair

GST REG. NO : M2 - 0020081 - X

29 JUL 2020

ESTIMATE

Estimate No. : b1 55637
Date Estimated : 29/07/2020
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Chan Wah Hak Nien Shen
12 Lucky Crescent

singapore 467734

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1132P	WBAHS120005J97008	28/06/2017	X1 sDrive18i	0

DESCRIPTION

VALUE

To replace rear boot lid, rear bumper include remove attachment etc

1700 2,550.00

Spray painting rear boot lid and rear bumper

1730 1,923.00

To replace rear windscreen glass.

574 676.00

To supply and install rear windscreen solar film.

? 625.00

To conduct water leak tests.

75.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To supply rear emboss number plate.

X 83.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451? 531.00

Sundries

? 150.00

Total Labour 1: 7,179.00

DESCRIPTION	QTY	PRIC	VALUE
SILENCER CLAMPING BUSH ?	1	54.60	54.60
RUBBER MOUNTING ?	2	17.70	35.40
REAR SILENCER ?	1	1,178.35	1,178.35
TAILPIPE TRIM BLACK CHROME ?	1	112.20	112.20
BOOTLID ?	1	1,236.65	1,236.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55637
Date Estimated : 29/07/2020
Prepared By : Chua Kee Sin

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1132P	WBAHS120005J97008	28/06/2017	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID LH HINGE X	1	79.75	79.75
BOOTLID RH HINGE X	1	79.75	79.75
RR BUMPER CARRIER ?	1	496.35	496.35
MOUNTING SMART OPENER ?	1	45.55	45.55
REAR TRIM UNDERRIDE PROTECTION (X L de -	1	190.80	190.80
RR BUMPER LH CORNER MOUNTING ?	1	142.65	142.65
RR BUMPER RH CORNER MOUNTING ?	1	142.65	142.65
Abrasion gua ?	1	2.55	2.55
Abrasion gua ?	1	2.55	2.55
REAR BUMPER PANEL PRIMED repair	1	903.40	903.40
REAR BUMPER MIDDLE TRIM PANEL (PDC) de -	1	265.65	265.65
REAR BUMPER TRIM BOTTOM (LINES) cut -	1	232.45	232.45
EMBLEM GROMMET ne /	2	0.85	1.70
BMW PLAQUE WITH ADHESIVE FILM ne /	1	71.60	71.60
LETTERING X1 ne /	1	64.45	64.45
STRIKER BOOT LID ?	1	59.80	59.80
LOCK TRUNK LID ?	1	229.10	229.10
SOFT CLOSE AUTOMATIC ?	1	612.10	612.10
BOOT LID/TAILOATE PUSH BOTTON ICAM ?	1	48.65	48.65
Lock plate ?	1	12.40	12.40
BUMP STOP ne /	10	3.75	37.50
REAR BUMPER TOWING EYE COVER X	1	36.80	36.80
REAR WINDOW (ESG) ? photo ?	1	851.00	851.00
HOOK AND LOOP FASTENER ?	4	2.85	11.40
HOOK AND LOOP FASTENER ?	4	2.85	11.40
CLAMP ?	4	2.39	9.56
AEROBLADE (SCHWARZ) ?	1	393.50	393.50
BOOTLID SEALING ne /	1	166.50	166.50
CLIP ne /	26	1.20	31.20
EXPANDING RIVET BLACK ne /	26	1.40	36.40
REAR LH REFLECTOR ?	1	38.85	38.85
ULTRASONIC SENSOR BLACK ?	4	249.95	999.80
DECOUPLING RING PDC TORQUE CONVERTER ?	4	5.10	20.40
(DG) CLEANER R1 (100ML) ne /	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) ne /	2	131.55	263.10
(DG/SL) ADHESIVE PRIMER VP 206 (30ML ne /	1	27.85	27.85

Total Parts : 9,262.51

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55637
Date Estimated : 29/07/2020
Prepared By : Chua Kee Sin

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1132P	WBAHS120005J97008	28/06/2017	X1 sDrive18i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 17/08/2020 @ 1349 Excess S\$ _____

Surveyor's Name Ryan Sign _____

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PM Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 5 days



Labour 1	:	7,179.00
Parts	:	9,262.51
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,150.91
Grand Total	:	17,592.42

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT:

Date Of Report	29/07/2020 15:39
Date Of Accident	29/07/2020 11:30
Exact Location Of Accident	JUNCTION OF ALEXANDRA AND LOWER DELTA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE:

Vehicle Registration Number	SLQ1132P
Insured/Policyholder	
Name Of Registered Owner	CHAN WAH HAK NIEN SHEN
NRIC No	SXXXX386B
Email Address	CCHANHC@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98000200
Alternative Phone No	OTHERS-81133366
Vehicle Particulars	
Manufacturer	BMW
Model	X1 F48
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM120042751900
Cover Note Number	
Driver	
Name of Driver	CHAN WAH HAK NIEN SHEN
NRIC No	SXXXX386B
Date Of Birth	27/02/1957
Occupation	INDOOR
Date Of Driving Pass	26/08/1991
Driving Experience	28 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98000200
Fax Number	
Contact Number	OTHERS-81133366
EEmail Address	CCHANHC@GMAIL.COM

Address 12 LUCKY CRESCENT
 Postcode 467734
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1 NAME: : CHAN PAIK POH
 GENDER: : FEMALE
 Passenger 2 NAME: : TIMONTHY SEE
 GENDER: : MALE
 Passenger 3 NAME: : LIM KOOI PENG
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number GBC2035Y
 Vehicle Make/Model/Colour TOYOTA WHITE
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver THAN HTUT OO
 NRIC/Passport Number
 Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

FRONT


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary while waiting to turn into Lower Delta Road near the junction of the traffic light (Lower Delta & Alexandra Road).
I was hit from behind while my car was stationary.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Alan Moh Hoi

Policyholder's Signature
Date & Time:

Alan Moh Hoi

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

29/7/2020

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

@ 14876

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	386B
Vehicle No.:	SLQ1132P
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Aug 2020
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I AT LED NAV
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G005H472B38A15A
Chassis No.:	WBAHS120005J97008
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,845.00
Original Registration Date:	28 Jun 2017
First Registration Date:	28 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$31,583.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2027
PARF Rebate Amount:	\$23,687.00

Intended COE Rebate Details

COE Expiry Date:	27 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$32,590.00
Total Rebate Amount:	\$56,277.00

The information contained herein is correct as at 17 Aug 2020

OK

art.com/used_cars/info.php?ID=917379&DL=1244

▶ BMW X1 sDrive18i

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$98,000

Depreciation ⓘ \$12,080 /yr
View models with similar depre

Reg Date 28-Jun-2017
(6yrs 10mths 10days COE left)

Mileage 62,300 km (19.8k /yr)

Manufactured ⓘ 2017

Road Tax ⓘ \$684 /yr

Transmission Auto

Dereg Value ⓘ \$60,373 as of today (change)

OMV ⓘ \$30,855

COE ⓘ \$55,000

ARF ⓘ \$30,197

Engine Cap 1,499 cc

Power 100.0 kW (134 bhp)

Curb Weight ⓘ 1,430 kg

No. of Owners ⓘ 2

Type of Vehicle SUV

Features

BMW TwinPower Turbo 3 Cylinder Engine With 138Bhp, 220Nm Of Torque. 0-100Km/H In 9.7s, Top Speed Of 200Km/H, 6 Speed Transmission, Front Wheel Drive. View specs of the BMW X1 (2015)

Accessories

IDrive With GPS, Bluetooth, Contactless Boot Release, Front And Back Sensors, Adjustable Rear Seats, Keyless Entry, Multi Function Steering Wheel.