

CS3/CTI19019055/Evf3-1

2/00/2001

ASS. REC. BY:

REF: ~~CS3/CTI19019055/Hcl/3/2~~

Special Instruction:

Surveyor: ~~Hock Ann~~ Steve

ASSIGNMENT (Office)

30/7/20

From (Person): ~~Chun Bin Sin~~

of CTI

Date/Time: ~~29.10.19 1.23pm~~

Estimated Cost: Jenny Lew

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 54285

Insured: SKW 9067Y

at Workshop n/s: Xin Yun Auto

Tel: 98391555

of Blk 8 Kaki Bukit Ave 4 #05-23 Premier

Policy No: DMPCSN 30736819000

Claim No: SVM 190205057 C12

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. ^{2/19} 26.10.2019

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 29.10.19 1.28pm

Person Contacted: Li Ping

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SMD 54285 - NBA / CTI 19019055 / Y DOA - 23/10/2019
	SKW 9067Y - NBA / CTI 19019055 / Y DOA - 23/10/2019
08/11/19	Submit PRS.
	Dismantle: 30/10/2019.
	After repair: 1/11/2019
5/8/20	Submit LS \$3700 (Red 3300, 47%)

123 H-ANN

ASSIGNMENT

From: _____ Core: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMD 54285
 at Workshop no: Yin Yee Auto private limited
 of Blk 8 Haki Bukit ave 4 #05
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMD 54285 Yr Regn: 24/08/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: H. Shuttle cc 1476
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 137092 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: 4071213369
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/60/105
 R: 185/60/115

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

NIS	O/S
X	X

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fit and for same (size)

Front: R/Bal. 6 mm L/Bal. 6 mm
 Rear: R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 23/10/19 D.O.I. 29/10/19

Bal or Market Value: _____
 IDAC: Accident Rpt Consistent? Yes or No
 GIA: PR Seen Consistent? Yes or No
 Est. Repairs 3 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

Survey held at Yin Yee Auto
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or _____

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range → 2800 - 3500
	mv - 76000
	pv - 37613
	nv - 38300

Date/Time: Pre Final? : Prelim Report
 08/10/19 : Final Report

Days Of Repair: 3 5

Resurvey No. of Trip: 2

Survey Fee:	190
Transportation:	
S + RS \$:	
Plates:	
Others:	
Total:	190

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Wash and

5/8/20-Typist

TPS.TP
 LS \$3700