



Your Ref: 19/19/19/VP02/299734

Date: 13th Aug 2020

Our Ref: CS1/LPM20007929/Avf3e2

M/s Lonpac Insurance Bhd

21St Flr, Bangunan Public Bank

NO. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMG 2878E

INSURED VEHICLE: JPH 237

ACCIDENT DATE: 06/12/2019

We thank you for your instruction on 03/08/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMG 2878E from M/s Priority Services.
- b) Polis Diraja Malaysia of Vehicles SMG 2878E, VCF 7127, JQB 1375 and JPH 237.
- c) Colour damaged vehicle photographs of SMG 2878E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMG 2878E
Make & Model	: Nissan Sylphy 1.6 CVT
Year of Registration	: 2018
Chassis Number	: MNTBBAB17Z0033835
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.