



PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC20008003/Qvf3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSE		Date: 06-08-2020		
SINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YM 6368K	Veh. Inspected	GBK 639B	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023509	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	03/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 DX AUTO	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	VM20140456	Colour	SILVER	
Odometer	9576 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14C	DUNLOP	6 mm	
L/H Front Tyre	175/70 R14C	DUNLOP	6 mm	
R/H Rear Tyre	175/70 R14C	DUNLOP	6 mm	
L/H Rear Tyre	175/70 R14C	DUNLOP	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
Accident Date	30/07/2020	Inspect Date / Time	04/08/2020 (02:06 PM)	
Survey held at	BLK 4 YEW TEE IND EST 399 - J			
Repairer	ENG SOON PAINTING SVC			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC20008003/Qvf3e2

Inspected By



OI SUN PIN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.