

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Aug 2020 09:13 Sendback Est	04 Aug 2020 09:20 S\$3,334.25	04 Aug 2020 11:37 Edit Adj Rpt	S\$1,593.00 Edit Estimates	S\$1,593.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: XXX		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHC2905R	Date of Loss:	02/08/2020 19:00 - :59 [33 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2003736	Policy/Cover Note No.:	MK000822 (Third Party Only) Coverage: 30/09/2019 - 29/09/2020
Vehicle Reg. No. (Insured):	SMH7056Y	Policy No. (Claimant):	
		Excess:	S\$3,000.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/08/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC2905R (M2003736)
[SMH7056Y]
TP
CTPL
Aug 2 2020 7:00PM
[CTPL]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports			1 per page	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	04/08/20 09:20	Repairer Estimates	1	Load HTM
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail Print
1	04/08/20 11:38	Accident Statement From:SC - Reg. No: SMH7056Y, Claimant: LUMENS AUTO PTE LTD	1	Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Adjuster Immediate Advice	1	(Protected)
Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	11/08/20 12:26	Odometer Reading	1	Load JPG
2	11/08/20 12:26	Chassis Number	1	Load JPG
3	11/08/20 12:26	General View	1	Load JPG
4	11/08/20 12:26	General View	1	Load JPG
5	11/08/20 12:26	General View	1	Load JPG
6	11/08/20 12:26	General View	1	Load JPG
7	11/08/20 12:26	General View	1	Load JPG
8	11/08/20 12:26	General View	1	Load JPG
9	11/08/20 12:26	General View	1	Load JPG
10	11/08/20 12:26	General View	1	Load JPG
11	11/08/20 12:26	General View	1	Load JPG
12	11/08/20 12:26	General View	1	Load JPG
13	11/08/20 12:26	General View	1	Load JPG
14	11/08/20 12:26	General View	1	Load JPG
15	11/08/20 12:26	General View	1	Load JPG
16	11/08/20 12:26	General View	1	Load JPG
17	11/08/20 12:27	Replacement Part Photo	1	Load JPG
18	11/08/20 12:27	Replacement Part Photo	1	Load JPG
19	11/08/20 12:27	Replacement Part Photo	1	Load JPG
20	11/08/20 12:27	Replacement Part Photo	1	Load JPG
Documentation			1 per page	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	04/08/20 09:22	E-filed GIA report	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI20008008/T1SF3S2**Date:** 13/08/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000822	
Claimant Vehicle No :	SHC2905R	Insured Vehicle No :	SMH7056Y	
Date of Loss:	02/08/2020	Nature of Claim:	TP	Claim No: M2003736

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2905R	Engine No:	2ZRS081584
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU003569136
Reg. Date:	06/10/2017 (Man. Year: 2017)	Odometer:	595619 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,083.25	512.00	1,571.25	75.42
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,240.00	1,070.00	170.00	13.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,334.25	1,593.00	1,741.25	52.22
+ GST 7.00/7.00% (S\$)	233.40	111.51	121.89	52.22
Nett Amount (S\$)	3,567.65	1,704.51	1,863.14	52.22

INSPECTION

Date of Assignment:	04/08/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	03/08/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2905R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR FENDER RH	Repair	836.70 FL	-	*- FL
2	1		*REAR DOOR RH	Repair	1,258.30 FL	-	*- FL
3	1		*ROCKER PANEL GARNISH RH	Deformed	576.00 FL	-	*576.00 FL
4	1		*REAR DOOR APPS STICKER RH	Necessary	80.00 F	-	*80.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	2,751.00	656.00
- List Item Discount on L Items 25.00/25.00% (\$)	667.75	144.00
Total Parts (\$)	2,083.25	512.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TUFF KOTE	New	40.00	30.00
2	PANEL BEATING	New	700.00	640.00
3	SPRAY PAINTING	New	500.00	400.00
Gross Labour Cost (\$\$)			1,240.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >