

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305414307
 REGN NO : SHD4454G
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 23.01.2020
 DATE/TIME IN : 03.08.2020 09:15
 ACCIDENT DATE : 29.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	Rp
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	de
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nee ✓
0004	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	x nn.
0005	FNPS	NO PLATE(S)	1 N	25.00	10.00	22.50	nn ✓

SUB-TOTAL : 818.62

JOB NATURE

0000	PB	PANEL BEATING	400.00	320
0001	SP	SPRAYPAINT CHARGE	300.00	200
0002	L	REMOVE/REFIX REVERSE SENSOR	80.00	300 550

SUB-TOTAL : 780.00

Tanpin 1749 5749
 401.50 'wp' 3/8/2020 3pm
 550
 02 days
 4951.50 # Resurvey after repair
 02 days
 Tanpin 1749 5749

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: