

ASS. REC. BY:

REF: CS/CTI20008021/Btf3

Special Instruction:

Surveyor: LIM

ASSIGNMENT (Office)

From (Person): Cecilia Low of CTI Date/Time: 04 Aug 2020 11:34

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 780S Insured: SJX 1771G

at Workshop m/s Team Auto Pro Pte Ltd Tel: 6258 1955

of 160 Sin Ming Drive #01-14 Sin Ming Autocity

Policy No: DMPCSNW00052312003 Claim No: SNM20D202705

Sum Insured: Excess:

Make of Veh: D.O.A. 01/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 4-8-20 1.20 P.M Person Contacted: PEACH Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SMK 780S- X
	SJX 1771G-CC4/AXA11000262/Rw2fk2 DOA :16/12/2010