

ASS. REC. BY: TG Lim

REF:

CS/CT126008021/Btf3

Denise

ASSIGNMENT

From: _____ Date: 4/8/2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNK 8780Sat Workshop m/s Dean Autoproof 160 Sim Ming Dr, #01-14

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: 59,000 @ DOA

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNK 8780S Yr Regn: 26/4/2019Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit GFKPkg C.C. 1317Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 48079 T/Radio: Insured / Std / NI / NAEng/No: L1381455756C/No: GK31346859Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/65/14 KINFORESR: 175/65/14 YOKOHAMA

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kinfore

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 1/8/2020 D.O.I. 4/8/2020Survey held at Dean Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| | Range 4,000/2 - 5,000/2 |
| | L/S 4,600/2 Telim Lim 14/8/2020 (Red: 14104.96: 75%) |
| | MV 59,000/2 |
| | PV 29,217/2 |
| | NV 29,783/2 |
| | Telim Lim 14/8/2020 |

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Formel: TPLump Sum / L.B.I. (\$) \$4600Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 01/08/2020 (dd/mm/yy) Time of Accident: 16.50 (24-HR-FORMAT)
Vehicle No.: SMK 8780 S Vehicle Make & Model: HONDA FIT 1.3G
Exact location of Accident: PASIR RIS DRIVE 1
Policyholder's Name / IC No.: YAP KUN S7534525I
Driver's Name / IC No.: YAP KUN S7534525I (As Above) ☐
Driver's Contact No.: 9437 7886 Company Contact No.: _____
Driver's Address: 456 TAMPINES STREET 42 #06-282 S520456
Insurance Company: NTUC Email address (if any): DAVE_YEKUN@YAHOO.COM

Relationship between Owner & Driver: OWNER

or Others specify: _____

What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle
Was being used at time of accident?

Occupation (nature of job) ☐ Indoor/ ☒ Outdoor

☐ Private use / ☒ Work purpose

No. of Passengers (Including Driver): 02

Passenger Name : GRAB HITCH FLORENCE TAN

Gender : Female

Passenger Name : _____

Gender : _____

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☒ Yes / ☐ No (If YES) Injured Person's Name: YAP KUN

Injuries Sustain: NECK Injured Person in Which Vehicle: SMK 8780 S

Police Report filed: ☒ Yes / ☐ No (If YES) Which Police Station: TAMPINES N.P.C

The Other Party(s) Details:

1. Driver's Name / IC No.: _____ Vehicle No: SJX177167

Driver's Contact No.: _____ Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No: _____

Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' SMK 8780S was travelling on the stated venue. I was travelling straight in my lane, slowed down my vehicle and came to a complete stop as traffic was red. While waiting, I felt an impact on my vehicle rear portion. Shortly I got out and realised vehicle 'B' had collided against my stationary vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|--------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 5251 |
| Vehicle Details | |
| Vehicle No.: | SMK8780S |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 15 Aug 2020 |
| Vehicle Make: | HONDA |
| Vehicle Model: | FIT 1.3G F-PKG CVT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2019 |
| Engine No.: | L13B1455756 |
| Chassis No.: | GK31346859 |
| Maximum Power Output: | 73.0 kW (97 bhp) |
| Open Market Value: | \$15,154.00 |
| Original Registration Date: | 26 Apr 2019 |
| First Registration Date: | 26 Apr 2019 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,154.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 25 Apr 2029 |
| PARF Rebate Amount: | \$3,865.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 25 Apr 2029 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$29,159.00 |
| COE Rebate Amount: | \$25,352.00 |
| Total Rebate Amount: | \$29,217.00 |

The information contained herein is correct as at 15 Aug 2020

OK

DOA 1/8/2020

COE left 8 yrs 8 mths

Dep 7070/yr
589/mth

MV @ DOA

MV 59,000/2

PV 29,217/2

NV 29,783/2

TGLim lim
14/8/2020

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SMK 8780 S**
 Model : Honda Fit
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: 2019

| Nos. | PARTS | Qty | Unit S\$ | TOTAL S\$ |
|------|-------------------------------|-----|-----------------|--------------------|
| 1 | Tailgate | 1 | \$ 1,085.20 | \$ 814.20 1,085.20 |
| 2 | Tailgate logo | 1 | \$ 86.20 | \$ 35.00 86.20 |
| 3 | Tailgate inner lock | 1 | \$ 389.20 | \$ 197.40 389.20 |
| 4 | Tailgate weatherstrip | 1 | \$ 286.30 | \$ 286.30 |
| 5 | Tailgate inner trim board | 1 | \$ 486.20 | \$ 341.80 486.20 |
| 6 | Tailgate inner handle | 1 | \$ 105.20 | \$ 105.20 |
| 7 | Tailgate buzzer | 1 | \$ 286.40 | \$ 120.00 286.40 |
| 8 | Tailgate antenna sensor | 1 | \$ 389.40 | \$ 215.40 389.40 |
| 9 | Tailgate outer garnish | 1 | \$ 469.20 | \$ 469.20 |
| 10 | Tailgate no plate lamp | 2 | \$ 102.30 | \$ 204.60 |
| 11 | Tailgate solenoid switch | 1 | \$ 367.50 | \$ 367.50 |
| 12 | Tailgate windscreen moulding | 1 | \$ 205.30 | \$ 190.00 205.30 |
| 13 | Rear bumper | 1 | \$ 1,064.30 | \$ 575.00 1,064.30 |
| 14 | Rear bumper side retainer | 2 | \$ 38.60 143.60 | \$ 77.20 287.20 |
| 15 | Rear bumper bracket | 2 | \$ 103.50 | \$ 207.00 |
| 16 | Rear bumper centre garnish | 1 | \$ 148.60 | \$ 78.70 148.60 |
| 17 | Rear bumper reflector garnish | 2 | \$ 286.40 | \$ 177.20 572.80 |
| 18 | Rear end panel | 1 | \$ 1,045.80 | \$ 420.00 1,045.80 |
| 19 | Rear end panel top garnish | 1 | \$ 256.30 | \$ 198.00 256.30 |
| 20 | Spare tyre panel | 1 | \$ 986.40 | \$ 986.40 |
| 21 | Spare tyre panel top board | 1 | \$ 250.00 | \$ 250.00 |
| 22 | Spare tyre panel insulator | 1 | \$ 269.10 | \$ 269.10 |
| 23 | Spare tyre panel sponge box | 1 | \$ 486.30 | \$ 486.30 |
| 24 | Taillamp | 2 | \$ 853.40 | \$ 761.60 1,706.80 |
| 25 | Taillamp lower bracket | 2 | \$ 145.60 | \$ 291.20 |
| 26 | Rear fender inner trim board | 2 | \$ 473.50 | \$ 947.00 |
| 27 | Exhaust pipe | 1 | \$ 1,036.00 | \$ 1,036.00 |
| 28 | Exhaust pipe mounting | 2 | \$ 75.90 | \$ 151.80 |
| 29 | Exhaust pipe heat shield | 1 | \$ 201.40 | \$ 201.40 |

Parts Sub Total : \$ 4,201.50 14,268.70

20% Discount \$ 840.30 2,853.74

PARTS TOTAL : \$ 11,414.96

3,361.20

| Nos. | SPECIAL NETT | Qty | Unit S\$ | TOTAL S\$ |
|----------------------|--|-----|-----------|--------------------|
| 1 | Sundries | 1 | \$ 80.00 | \$ 80.00 |
| 2 | Tailgate sealant | 1 | \$ 100.00 | \$ 30.00 100.00 |
| 3 | Tailgate inner trim board clips | 1 | \$ 50.00 | \$ 30.00 50.00 |
| 4 | Tailgate outer garnish clips | 1 | \$ 50.00 | \$ 30.00 50.00 |
| 5 | Tailgate windscreen seal | 1 | \$ 60.00 | \$ 60.00 |
| 6 | Tailgate windscreen primer and cleaner | 1 | \$ 80.00 | \$ 80.00 |
| 7 | Tailgate windscreen sealant | 1 | \$ 120.00 | \$ 60.00 120.00 |
| 8 | Tailgate reflector clips | 2 | \$ 50.00 | \$ 100.00 |
| 9 | Tailgate reflector seal | 2 | \$ 60.00 | \$ 120.00 |
| 10 | Rear bumper clips | 1 | \$ 50.00 | \$ 30.00 50.00 |
| 11 | Rear bumper reflector garnish clips | 2 | \$ 50.00 | \$ 100.00 |
| 12 | Rear end panel sealant | 1 | \$ 100.00 | \$ 40.00 100.00 |
| 13 | Rear end panel top garnish clips | 1 | \$ 50.00 | \$ 30.00 50.00 |
| 14 | Spare tyre panel sealant | 1 | \$ 100.00 | \$ 100.00 |
| 15 | Rear no plate w/cowling | 1 | \$ 80.00 | \$ 80.00 |
| 16 | Rear bumper reverse sensor | 2 | \$ 250.00 | \$ 200.00 500.00 |
| 17 | Taillamp inner seal | 2 | \$ 60.00 | \$ 120.00 |
| 18 | Taillamp clips | 2 | \$ 50.00 | \$ 100.00 |
| 19 | Rear fender inner trim board clips | 2 | \$ 50.00 | \$ 100.00 |
| 20 | Reverse camera | 1 | \$ 480.00 | \$ 480.00 |
| SPECIAL NETT TOTAL : | | | | \$ 450.00 2,540.00 |

| Nos. | LABOUR | S\$ |
|----------------|-------------------------------|----------------------|
| 1 | R&R tailgate component | \$ 80.00 150.00 |
| 2 | R&R rear windscreen | \$ 120.00 250.00 |
| 3 | R&R upholstery | \$ 300.00 |
| 4 | R&R exhaust pipe | \$ 150.00 |
| 5 | R&R reverse sensor | \$ 60.00 80.00 |
| 6 | Check wiring | \$ 50.00 120.00 |
| 7 | Panel beat | \$ 800.00 1,600.00 |
| 8 | Diagnostic & reset fault code | \$ 300.00 |
| 9 | Rust proofing | \$ 60.00 200.00 |
| 10 | Spray painting | \$ 800.00 1,600.00 |
| LABOUR TOTAL : | | \$ 1,970.00 4,750.00 |

Survey 4/8/2020 Resurvey 5/8/2020
 TCCM Lin TCCM Lin
 1430hrs

PARTS TOTAL : \$ 3361.20 11,414.96
 SPECIAL NETT TOTAL : \$ 450.00 2,540.00
 LABOUR TOTAL : \$ 1,970.00 4,750.00
 GRAND TOTAL : \$ 18,704.96

Lump sum repair
 Repair days 7

@ 20%

5,781.20
 1,156.24
 4,624.96

L/S 4,600/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

