

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CS/AG/20008022/Uvf3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *52597D*
 at Workshop m/s: *Zony Automotiv*
 of _____
 Insured: *smm 1382*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *43*
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: *3* days Res.: Yes or No
 Lum Sum: *2* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A 3668

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *52597D* Yr Regn: *11/14*
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA /*
 Make: *VOLVO V40* *cross country 32* *1560*
 Colour: *white* A/C: Insured / Std / NI / NA
 Sp. Reading: *125727* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *YV1M2845BF2067089*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *In order* / Jammed / Leaked / Burnt or
 Brake: *In order* / Jammed / Leaked / Burnt or
 Modi: *Nil* / *6/Rim* / STD A/Rim or
 Tyre Size: F: _____ R: *245/352R19*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Roadstone*
 Front *6* Rear *6*
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *1/8/20* D.O.I. *4/8/20*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/5 Rf.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

next 6320

21/8/20 1/544250 confirmed with Zony (Red 5951-10, 5810)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *3*

1)

☐ : Final ReportResurvey No. of Trip: *2*

Date/Time, File Return to?

Survey Fee:

2) *24/8- typist*

Transportation:

Report Format: *TP*Lump Sum / I.B.I.: (\$ *4250* / *2*)

Add Fee: ☐ : Site Insp (\$) S + RS, SI
☐ : Interview (\$) Photos
☐ : Tech. Invs (\$) Others
☐ : Weekend (\$)

TOTAL

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 327I

Vehicle Details

Vehicle No.: SLS97D
Vehicle to be Exported: No
Intended Deregistration Date: 04 Aug 2020
Vehicle Make: VOLVO
Vehicle Model: V40 CROSS COUNTRY D2
Primary Colour: White
Manufacturing Year: 2014
Engine No.: D4162T3072106
Chassis No.: YV1MZ845BF2067089
Maximum Power Output: 84.0 kW (112 bhp)
Open Market Value: \$26,601.00
Original Registration Date: 26 Nov 2014
First Registration Date: 26 Nov 2014
Transfer Count: 1
Actual ARF Paid: \$14,242.00 714

Intended PARF Rebate Details


PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Nov 2024
PARF Rebate Amount: \$9,969.00

Intended COE Rebate Details

COE Expiry Date: 25 Nov 2024
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$62,000.00
COE Rebate Amount: \$26,711.00
Total Rebate Amount: \$36,680.00

The information contained herein is correct as at 04 Aug 2020


OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)




Post an Advertisement


Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an AdAdvertiser LoginWays of Selling

New 5 Years Renewal COE Toyota Vios 1.5A.



Wow! 2.5% P.A, \$438 Monthly
By GV Financing, \$0 Admin, \$0
Down, 2 Years Warranty
GV Credit Pte Ltd StarAd



PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.




Browse by Category

Sort by Date Posted20 results/page

Advanced SearchSubmit

3 vehicles

v40

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	v40		Any	Any	2014	Any	Any	Any	Available
	Volvo	V40 Cross Country Diesel D2	\$46,800	\$9,710 /yr	29-May-2014	1,560 cc	-	Hatchback	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Very Rare Blue Unit! Well-Maintained By Previous Owner. Fuel Efficient With Spacious Cabin & Boot Spaces. Flexible Loan Scheme To Su... Trust Motoring Posted: 03-Aug-2020 Tags: 2014 Volvo V40, Volvo V40, Volvo, V40									
	Volvo	V40 Diesel D2	\$42,800	\$9,210 /yr	09-Sep-2014	1,560 cc	126 km	Hatchback	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Well Maintained And Fuel Efficient. In Perfect Condition. Most Reliable Continental Hatchback With Powerful And Responsive Engine. Met... Edmund Motor Pte Ltd Posted: 01-Aug-2020 Tags: 2014 Volvo V40, Volvo V40, Volvo, V40									
	Volvo	V40 Diesel D2	\$43,800	\$9,130 /yr	31-Oct-2014	1,560 cc	99,000 km	Hatchback	Available
Fuel Type: Diesel (Euro 5 Engine and Above) Well Maintained And Fuel Efficient. In Perfect Condition. Most Reliable Continental Hatchback With Powerful And Responsive Engine. Met... Posted: 01-Aug-2020 Tags: 2014 Volvo V40, Volvo V40, Volvo, V40									

Save this search criteria, to get email alerts whenever a match is found.

MakeModelPriceDepreciationReg DateEng CapMileageVeh TypeStatus

For old advertisements, view Expired ads

20 results/page

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2020 17:16
Date Of Accident	01/08/2020 12:00
Exact Location Of Accident	121 WESTWOOD AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS97D
Insured/Policyholder	
Name Of Registered Owner	ONG CHAI PENG
NRIC No	SXXXX327I
Email Address	TONY07AUTO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91724810
Alternative Phone No	OFFICE-91724810

Vehicle Particulars

Manufacturer	VOLVO
Model	V40
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105516126-01
Cover Note Number	

Driver

Name of Driver	NICHOLAS SOH ZHI WEI
NRIC No	SXXXX065H
Date Of Birth	13/11/1997
Occupation	INDOOR
Date Of Driving Pass	05/10/2017
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91724810
Fax Number	
Contact Number	
Email Address	TONY07AUTO@GMAIL.COM

Address	121 WESTWOOD AVENUE
Postcode	648212
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMM1380Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN HAN MENG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/ or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 03.09.20


Driver's Signature

(If driver is not the policyholder)

Date & Time: 03.09.20


Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A - SLS97D
B - SMM13802



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 1/8/20 at around 12pm, I was driving my vehicle SLS97D along Westwood Avenue when a vehicle SJU9139X turned out from Westwood Residences, with initial intention of turning left. But vehicle SJU9139X did a sudden right turn which collided with my vehicle. I have video evidence.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 6.3.06.20

Driver's Signature

(If driver is not the policyholder)

Date & Time: 6.3.06.20

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:



Tony Automotive Pte Ltd

Not Authorised
N/A
4/8/20
1/5 @ 42501
3 days.
the shop after rep-

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875
Tel: 69763261 Fax: 69763271
Email: tony07auto@gmail.com
Co. Reg No.: 201939168R

ESTIMATE

Model: **VOLVO V40 D2**

Veh No: **SLS97D**

Qty	List Items	Amount S\$
1	FRONT BUMPER <i>1660</i>	Dis 2350
2	FRONT BUMPER LED FOG LAMP @ 720 <i>420</i>	0/Scra 1440 1pc
2	FRONT BUMPER LOWER CENTRE GARNISH @ 340	0/Scra 680 1pc
1	FRONT BUMPER BOTTOM COVER GARNISH	ns 430 X
2	FRONT BUMPER SIDE RETAINER @ 95	11 190 X
2	FRONT BUMPER SIDE BRACKET @ 160	11 320 X
1	FRONT BUMPER TOW HOOK COVER <i>45</i>	Tofa 154
1	FRONT BUMPER REINFORCEMENT	Beaf 860
1	FRONT BUMPER CENTRE FRAME	11 325 X
1	FRONT HEADLAMP RH <i>1655</i>	scrkne 1680
1	FRONT HEADLAMP LOWER BRACKET RH	11 150 X
Sub Total		8579
Less 10%		857.90
		7721.10

Special Nett Items

Qty	List Items	Amount S\$
1 SET	FRONT BUMPER CLIP	80 <i>50</i>
Sub Total		80

Qty	Labour charges	Amount S\$
1	TUFFKOTE	11 200 X
1	TO PUTTY, SPRAY PAINT ETC	1200 <i>400</i>
1	TO PANEL BEAT, WELD, ALIGN ETC	1000 <i>400</i>
Sub Total		2400

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$ \$10,201.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p-4980
102
p-4482
S.N-50
L-800
5332
202
4265