Serveyor:		REF: CS1/LPM:	20008033/Esf3		Special Instruction:	
From (Person) Estimated Cos	: Ko Siew Ling	of LPC D	MENT (Office) ate/Time: 17/0	7/2020	Third Parties: Claimant: Ov	
OD/TP Re-in:	spection / Evaluat	tion			Surveyor: CA	
	hicle No: S	LN 704EC	Insurad: \M	NIC 8203	Workshop: AE	Auto
		04	Insured: W			
of <u>160 Sin</u>	Ming Drive #06)-()	_ 101930		4	
Policy No:			Claim No: 19/20	n/20/\/P96	/304742	
Sum Insured:_			Excess:	0/20/1/30	1004142	
Take of Vell.			_ EXCESS	2/2020		
Client's Record)	w #		_D.O.A0010	2/2020		
Date/Time: _		Person Contacted:	Vehicle	IN/OUT	O.D. Endorsement/Date	
Date/Time:	Confir	med with Fina	I Fig, _	days (Red	\$/%; 0	riginal 18 days)
Date/Time:	Submi	t Final Fig	days (Red	\$/_	%; Original	_days)
Date/Time	Action/Instruction					
	SLN 7845S -	X				
			W			
Para(1): F	Parts found not	replaced (To hig	hlight R or	TIR ID	F(a)	
		Table (10 mg	might A 01	UB, LK	, ElC)	
'						
Para(2) : (Comments on c	onsistency of dama	ges (Parts Not	Consister	it:NC)	
	 					
Para(3) : N	Nett Value					
			T	•	Fee Channel	
	Market Value :		Inspected/ Evaluated by:		Fee Charged: Basic & Add	Date:
					Transport	
		-			Photos	
	Nett Value	:			Others Total	
1) Date/Time	Fi	le Pass to	2) Date/Time_		File Return to	L
3) Date/Time	Fi Fi	le Pass to	4) Date/Time			
5) Date/Time	• Fi	le Pass to	6) Date/Time	AND SELECTION OF THE PARTY OF T	File Return to	