

Lke

CHINA

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.07.2020

Time: 12:17:29

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305413844
 REGN NO : SHD7140S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 10.11.2016
 DATE/TIME IN : 30.07.2020 08:45
 ACCIDENT DATE : 29.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	de ✓
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	ner ✓
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	228.00	20.00	182.40	ent ✓
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00-	135.70	nu ✓
0005 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	0.20	50.00	ner ✓
0006 04-01-0103-0581-A	I40VC LAMP ASSY-RR COMB O	1 L	697.80	20.00	558.24	✗
0007 03-01-0103-0121-G	I40VC GUARD ASSY-RR WHEEL	1 L	174.90	20.00	139.92	✗

SUB-TOTAL : 1,968.66

JOB NATURE

0000 L	PANEL BEATING (repair rr fender Lh)	500.00	280
0001 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	200
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	✗

Tanpin 97495749
 WP
 clb coming after repair
 30/7/2020 4pm
 02 days
 tanpin e (khandu.w.n.)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.07.2020

Time: 12:17:29

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305413844
REGN NO : SHD7140S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.11.2016
DATE/TIME IN : 30.07.2020 08:4
ACCIDENT DATE : 29.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 20-22 REMOVE/REFIX REVERSE SENSOR

120.00 ~~30~~

SUB-TOTAL : 1,170.00

TOTAL : 3,138.66

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

215, River Valley Road, Singapore 170211
Mainline - 65 6280 8280, Faxline - 65 6280 8190

Workshops

215 River Valley Road, Singapore 170211
215, River Valley Road, Singapore 170211
40, Telok Ayer Street, Singapore 069898
220, Telok Ayer Street, Singapore 069898

215 River Valley Road, Singapore 170211
215, River Valley Road, Singapore 170211
40, Telok Ayer Street, Singapore 069898
220, Telok Ayer Street, Singapore 069898

Date/Time: 30.07.2020 11:49

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JO NO. 305413844

CUSTOMER
COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)
(R)
(P)


REGN NO.	SHD7140S	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	I-40	DATE/TIME IN
YR OF MANU.	10.11.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMHU096298	COMPLETION DATE/TIME

CHINA

Accident Date: 29.07.2020
NATURE: 3P 29.07.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHD7140S

LKE

Taufik

Vehicle No.

SHD7140S

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard