

(08/11/13) wef

ASS. REC BY: Marcus

REF:

CS/CT120008045/UVF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 4288A

at Workshop m/s

of

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$148k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3

days

Res.: Yes or No

Lum Sum: 2

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 25039

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: XE 4288A

Yr Regn: 9 / 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: ISUZU

EXR52C

c.c

15681

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 126268

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JALEXR52E37000055

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

295 / 80 R 22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Annate

Front

Rear

R/Bal. 40% mm 4

R/Bal. 40% mm 4

40% mm 4/4

L/Bal. 40% mm 4

L/Bal. 40% mm 4

40% mm 4/4

D.O.A. 17/4/20

D.O.I. 4/8/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

2/8/20 4/5 \$3500 confirmed with MR Wong (Red 3480.65, 50%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 24/8 - typist

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

) S + RS, SI

) Photos

) Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I: (\$ 3500/2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	442H
Vehicle Details	
Vehicle No.:	XE4288A
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Apr 2020
Vehicle Make:	ISUZU
Vehicle Model:	EXR52E
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	6WG1436193
Chassis No.:	JALEXR52EJ7000055
Maximum Power Output:	-
Open Market Value:	\$96,754.00
Original Registration Date:	03 Sep 2018
First Registration Date:	03 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$4,838.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,902.00
COE Rebate Amount:	\$25,039.00
Total Rebate Amount:	\$25,039.00

The information contained herein is correct as at 18 Apr 2020

OK

Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore.
You can read customers' reviews & ratings on their services too.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

2013 Full Spec Estima, Mint Condition



FOC 1 Year Liberty Extended
Motor Warranty
HTS Motor StarAd

ABWIN 



» Visit Our Profile «

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

Isuzu EXR52E

Advanced Search  Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Isuzu	EXR52E	Any	Any	Any	Any	Any	Any	Available
	Isuzu	EXR52E (New 10-yr COE)	\$69,800	\$6,980 /yr	26-Oct-2010	15,681 cc	-	Truck	Available
Fuel Type: Diesel Super Genuine Low Mileage! Exclusive Warranty Package To Be Given! Free Servicing! Prime Mover! Rare Manual Transmission Unit Wit... Car (S) Pte Ltd Posted: 04-Aug-2020 Tags: 2010 Isuzu EXR52E, Isuzu EXR52E, Isuzu, EXR52E									
	Isuzu	EXR52E	\$49,800	\$14,850 /yr	12-Dec-2013	15,681 cc	218,010 km	Truck	Available
Fuel Type: Diesel 1 Owner Isuzu EXR52E Prime Mover. Low Usage. Well Maintained By Previous Owner. No Repair Needed. 100% Financing. Fast Loan Ap... Think One Automobile & Trading Posted: 31-May-2020 Tags: 2013 Isuzu EXR52E, Isuzu EXR52E, Isuzu, EXR52E									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Rental Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Isuzu EXR52E, Isuzu EXR52E Singapore, used Isuzu EXR52E Singapore, used Isuzu EXR52E, used vehicles Singapore or even buy used Isuzu EXR52E Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2020 sgCarMart, Singapore. All rights reserved.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2020 14:36
Date Of Accident	17/04/2020 17:25
Exact Location Of Accident	PSA COMPLEX
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE4288A
Insured/Policyholder	
Name Of Registered Owner	LEGEND MOTORS & LEASING PTE LTD
Co Reg No	2XXXXXX442H
Email Address	ALAN.ANG@LEGENDLEASING.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-87991700

Vehicle Particulars

Manufacturer	ISUZU
Model	EXR52E-15.7 D (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VFX/P1847906
Cover Note Number	

Driver

Name of Driver	LIU ZHAOXIANG
Work Permit No	0XXXXX6445
Date Of Birth	08/10/1981
Occupation	OUTDOOR
Date Of Driving Pass	30/01/2018
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87806429
Fax Number	
Contact Number	
Email Address	CLAIMS@FOCUSAUTO.COM.SG

Address	BLK 73 JALAN WANGI #02-23 SENNETT ESTATE SINGAPORE 349386
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 391 NEW BRIDGE ROAD POLICE CANTONMENT COMPLEX BLOCK A , POSTCODE: 088762 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2369999 - FAX NO: 62268438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

As per police report T/20200417/2053

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL3815L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAY TIAN ENG
NRIC/Passport Number	
Contact Number	96224696
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature
Date & Time: 180420

Driver's Signature
(If driver is not the policyholder)
Date & Time: 31/18/4 945

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:



SKETCH PLAN

CARPARK

PSA COMPLEX

CARPARK



A - XE4288A

B - 4L 3815L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police report T/20200417/2053

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time 180720

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
ARIC/FIN No _____



POLICE REPORT 1



**SINGAPORE
POLICE FORCE**



T/20200417/2053

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

1 of 3

Report No T/20200417/2053

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/04/2020 20:16		Vide Report No.:		Station Diary No.: 122	
Informant's Particulars					
Name of Informant: LIU ZHAOXIANG			Address: APT BLK 73 JALAN WANGI #02-23 SENNETT ESTATE SINGAPORE 349386		
ID Type / ID No.: FIN NO / G8107367N			Contact No.: Home/Office: Mobile: 87806429		
Nationality: CHINESE			Email:		
Sex: Male	Age: 38	Date of Birth: 08/10/1981	Type of Informant: Driver		
Race: Chinese			Language: Chinese		Institution / School Name:
Occupation: PSA LORRY DRIVER			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 17/04/2020 17:30	Type of Location: Car Park
Location: Along Road 1 KAMPONG BAHRU ROAD inside PSA complex				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
XE4288A	Lorry	ISUZU	EXR52E	Black	Seriously Damaged	0
YL3815L	Lorry	MITSUBISHI	FK617MSJR DEC	White	No Damage	1


Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT 2



**SINGAPORE
POLICE FORCE**



T/20200417/2053

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

2 of 3

Report No. T/20200417/2053

CONTINUATION OF REPORT

Driver			
Name	LIU ZHAOXIANG	ID No.	G8107367N
Related Vehicle	XE4288A (Lorry)	Contact No.	87806429
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAY TIAN ENG	ID No.	S2168904A
Related Vehicle	YL3815L (Lorry)	Contact No.	96224696
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/04/2020 at about 1730hrs, I was working and driving my lorry (XE4288A) in the PSA complex. While I was about to reverse my lorry into a parking lot, another lorry (YL3815L) carrying goods drove past my lorry's left side. This resulted in the other lorry's goods scratching against the left side of my lorry. My lorry sustained major damages at the front left of my lorry such as the whole left mirror spoiling and also part of the frame came off. The other lorry did not have any damage as it was the goods that collided with my lorry. The other lorry had one passenger and there was no injuries on all parties. No police or ambulance was at scene.

I would state that the standard practice inside the PSA complex is for all vehicles to wait patiently behind a vehicle that is reversing. A vehicle can only continue driving forward if the front vehicle have fully completed the parking process and when there is a safe distancing between the two vehicles.

I am lodging this report for my insurance's claims.

POLICE REPORT 3



SINGAPORE
POLICE FORCE



T/20200417/2053

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

CONTINUATION OF REPORT

3 of 3
Report No. T/20200417/2053

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: A / Sgt 2 CHUA REN YOU	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/04/2020 20:16
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:

Authentication Stamp
NP168



Signature

Singapore Police Force

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

not Authorised
 2/5 3500
 4/8/20
 Take photo After repair
 3 days.

M/S : CHINA TAIPING**Estimate No: M00159**

Date: 19-May-20

Veh Reg No : **XE4288A**

ATTN: Motor Claim Department

Make/Model : ISUZU EXR52E

Your Ref No: **XE4288A**

Chassis No: JALEXR52EJ7000055

Claim Type: THIRD PARTY

Engine No: 6WG1436193

Accident Date: : 17.04.20

Reg. Date : 03.09.20

Estimate Repair Cost to Vehicle No : XE4288A

PAGE:1/2

S/N	Description	Quantity	Unit	Price	Amount
				<u>SS</u>	<u>SS</u>
1	Front Coner Panel - LH 725.15	1	PCS	856.00	856.00 ✓
2	Front Coner Panel Rubber Seal - LH	1	PCS	50.00	50.00 ✓
3	Front Bumper 2260.15	1	PCS	2984.00	2984.00 ✓
4	Front Bumper Coner Garnish - LH	1	PCS	140.00	140.00 X
5	Front HeadLamp Rim - LH	1	PCS	280.00	280.00 X
6	Front Step Panel Garnish - LH 525.00	1	PCS	689.00	689.00 ✓
7	Front Slide Mirror Support - LH	1	PCS	460.00	460.00 ✓
8	Front Side Mirror Top Bracket - LH	1	PCS	160.00	160.00 X
9	Front Side Mirror Support Garnish - LH	1	PCS	60.00	60.00 X
10	Front Side Mirror - LH (Top)	1	PCS	260.00	260.00 X
11	Front Side Mirror Lower - LH	1	PCS	260.00	260.00 ✓
12	Front Lower ^{corner} Coner Garnish - LH 166	1	PCS	190.00	190.00 ✓

TOTAL	6389.00	6389.00
DISCOUNT 15%	5430.65	5430.65

LABOUR CHARGES

- 13 Panel Beating
 14 Check Wiring
 15 Rust Proofing
 16 Spray Painting

P-4448.30
 15%
 P-3779.35
 L-620.00
 4399.35
 20%
 3519.

300 850.00
 20 60.00
 11 60.00 X
 300 580.00

TOTAL	1550.00
--------------	----------------

OVERALL TOTAL	6980.65
----------------------	----------------

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

M/S : CHINA TAIPING

Estimate No: M00159

Date: 19-May-20

Veh Reg No : XE4288A

ATTN: Motor Claim Department

Make/Model :ISUZU EXR52E

Your Ref No: XE4288A

Chassis No: JALEXR52EJ7000055

Claim Type: THIRD PARTY

Engine No: 6WG1436193

Accident Date: : 17.04.20

Reg. Date :03.09.20

Estimate Repair Cost to Vehicle No :XE4288A

PAGE:2/2

FOR FOCUS AUTO PTE LTD

AUTHORISE SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: