

COMFORT DEL GRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 30.07.2020
Time: 16:24:18
Page: 1

QBE - R/S
LKE - Taufik

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS: CITYCAR PTE LTD
181 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305414081
REGN NO : SHB3114E
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 21.10.2016
DATE/TIME IN : 30.07.2020 13:45
ACCIDENT DATE : 30.07.2020

JOB PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	REAR BUMPER	1	458.60	25.00	343.95	de
0002 04-01-0302-2287-G	REAR BUMPER CENTER-Black	1	552.60	25.00	414.45	de
0003 04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50	de
0004 04-01-0302-0795-A	TAILLAMP LWR RH	1	548.40	25.00	411.30	crn
0005 09-01-0302-2005-A	REVERSE SENSOR	1	135.70	250	135.70	X ny
0006 04-01-0302-2965-G	REAR BUMPER EXTENSION RH	1	232.00	25.00	174.00	RY

1176.20.

SUB-TOTAL : 1,495.90

JOB NATURE

0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00	ny
0001 20-05	Rear Bumper Adv.Sticker	50.00	ny
0002 PB	PANEL BEATING	350.00	320
0003 SP	SPRAYPAINT CHARGE	250.00	200
0004 L	R/I REVERSE SENSOR	120.00	50

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.07.2020

Time: 16:24:18

Page: 2

IS

QBE - CLS
LKK - Taufik

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305414081
REGN NO : SHB3114E
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 21.10.2016
DATE/TIME IN : 30.07.2020 13
ACCIDENT DATE : 30.07.2020

JOB PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0005 17-01

CHECK ALL LIGHTING

30.00

30 ✓ 830

SUB-TOTAL : 1,000.00

TOTAL : 2,495.90

VA NAME & SIGNATURE
ATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Taufik 97495749
wp'

2 days 30/7/2020 Spr.
US Resurvey after repair
taufik @ lkkhandson.com

1176.20

830

2006.20

CLS \$1600

2 days #

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: