

ASS. REC. BY:

Tang

REF:

CTI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

01/01/19

Veh No:

SHB 21995

Yr Regn:

2016, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai 140

c.c. 1685

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

624515

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM HLB41UM6U4582Y

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205 / 60R16

R:

u a

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

3/8/20

Survey held at

Confidential Agency

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooktop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Workshop (\$

Per. Format:

Lum Sum / B.I.C.

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

53 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 573717
45 Pandan Road Singapore 609285

24 Bannock Road Singapore 758156
7 Sungei Kadut Way Singapore 708791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 03.08.2020 14:38

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.: 305414446

STOMER

CITYCAB PTE LTD
7010070
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188

(P) (O)

COUNT CARD NO.


REGN NO.	SHB2199S	MILEAGE
MAKE	HYUNDAI	FUEL
MODEL	I-40	DATE/TIME IN
YR OF MANU	21.04.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU088824	COMPLETION DATE/TIME:

Accident Date: 02.08.2020
NATURE: 3P 02.08.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION

TAKE PHOTOGRAPH
BEFORE / AFTER
SPRAY PAINTING



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.

SHB2199S

OLIVIA

Vehicle No.

SHB2199S

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard