

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD Ref : CS/CTI20008096/Gvf3e2				
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date: 18-08-2020 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SMJ 7390X	Veh. Inspected	SMK 6559D
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNM20D202010C02	Excess (\$)	0.00
	Assign From	IRENE TAY	Assign Date	05/08/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL 1.5X	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	RU11315396	Colour	PURPLE
	Odometer	34005	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45Z R18	FALKEN	5 mm
	L/H Front Tyre	225/45Z R18	FALKEN	5 mm
	R/H Rear Tyre	225/45Z R18	FALKEN	5 mm
	L/H Rear Tyre	225/45Z R18	FALKEN	5 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
	REPAIR CONDITION SEE DETAILS.			
5.	General Information			
	Accident Date	28/05/2020	Inspection Date	12/08/2020
	Survey held at			
	1 KAKI BUKIT AVE 6#01-59 SINGAPORE 417883			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			