f3-1

ASS. REC. BY:
Surveyor: Adnan
Mohmen
REF: C8/AIG/9021393/At 3
Special Instruction:

ASSIGNMENT (Office)

From (Person): Jennifer chan of AIG Date/Time: 3/12/19 @ 4:59pm

Estimated Cost: Bill to:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 7171J Insured: SKN1018P

at Workshop m/s U2 spray painting Tel: 8618 6474

of 25 kaki Bukit Road 4 #06-43

Policy No: Claim No: 423457616 ISG

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 26/11/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 9:37am @ 4/12/19 Person Contacted: Ah huat Vehicle IN / (OUT)

Date/Time	Action/Instruction
	Estimate ✓
	SJV7171J-CC8/AIG/1025548/RaJily DOA: 10/12/2011
	SKN1018P- CC3/AIG/6012514/ Avbe J DOA: 3/7/2016
	Submit DAR Report