ASS. REC. BY: CASUL NEF: CS/ICS 200	OS112/ f3   OS8A  CONTENT WEXDIRY: 2022/APR
ASSI	GNMENT
	Veh No: SKE 9660D Yr Regn: 2012   MP
From: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry /. Taxl / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	1 : 1 - 15-50 LUTL - 1290
To Inspect Vehicle No: SKC 9660	1004181181
at Workshop m/s \\A\A\A\	Colour
of 48, 10 H hum for com	op.ineading III Dr.
Insured: ICS	Eng/No:
Policy No.	C/No: WV WZZZ 167CM 093707 .
Claims No.	Gen. Cond: Good / Falt/ Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: horder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / STRim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R:
(Policy Condition)  Remark: The yeh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (FIR / SUMI )
repair at the time of inspection.	TOYO / YOKO or -
Bal. or Market Value: 28K	-   Tish
IDAC Accident Rport: Consistent? : Yes or No	I Tool
GIA / PR Seen: Consistent? : Yes or No	U/Bal. 6 mm U/Bal. 6 mm
Est. Repairs:days Res.: Yes or No	D.O.A. 20/07/2020
Lum Sum: % 3 Val.: Yes or No	Survey held at VAS
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU  Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time   Action / Instruction	
•	* .
4	
ži ,	
Note that the second	
ale/Time, File Pass to? : Preli. Report	Days Of Repair:
and a converse sequel of the first of the fi	Resurvey No. of Trip: Survey Fee:
; Final Report	leaned and
; Final Report	Transportation:
) : Final Report : Date/Time, File Return to?	Transportation:
) ; Final Report	Transportation:  Site Insp (\$ )_s+Rssi
) : Final Report  Date/Time, File Return to?  Add F	Transportation:
; Final Report  Date/Time, File Return to?  Add F	Transportation:  -ee: :Site Insp (\$ )s+Rssi  :Interview (\$ ) Photos  :Tech, Invs (\$ ) others
) : Final Report Date/Time, File Return to? Add F	Transportation:
; Final Report  Date/Time, File Return to?  Add F	Transportation:  -ee: :Site Insp (\$ )s+Rssi  :Interview (\$ ) Photos  :Tech, Invs (\$ ) others

#### Repair Estimate



VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax 6267 9313

www.avantage.sg

Date: 1-Aug-2020

Chassis No: WVWZZZ16ZCM093707

Vehicle Num : SKE9660D

Make/Model: VW Jetta 1.4

T	PARTS		QTY		PRICE		TOTAL
N	1 7		1	\$	761.25	\$	761 25
1 1	Rear Bumper		1	\$	507.50	5	507.50
2 F	Rear Lower Spoiler & /			s	141.89	s	141.89
	oam Insert		1		451.50	s	451.50
4 F	Reinforcement .		11	\$			
5 0	Centre Guide Pc 7		11	\$	80.85	\$	80.85
	H Guide Pc .		1	\$	89.25	5	89.25
1			1	\$	89.25	\$	89.25
F	RH Guide Pc						
+		1					
+	LKK Auto Consultants hence notify						
+	the Repairer of the following:						
1	To resurvey before/after spray painting	1					
1	To display damaged part(s) during resurvey					-	
+	Parts prices are subject to confirmation						
+	Third party survey is on a "Without Prejudice" basis	1					
1	No illegal modification(s) is allowed						
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company					$\vdash$	
				_		-	
	Acknowledged by Repairer	TOTAL PARTS		_		\$	2,121.49
	Signature:	Less 10%				\$	212.15
		TOTAL AMOUNT				\$	1,909.34
	MISCELLANEOUS ITEM					+	
1	Sundries			\$	30.00	\$	30.00
2	Reverse Sensor 🗡			\$	200.00	\$	200.00
	LABOUR					-	
	Remove and Refit Rear Bumper, Lower Spoiler, Foam Insert, Rei Guide Pcs and other associated components.	inforcement,		\$	560.0	0 \$	250 56000
				s	400.0	os	250 4000
	Surface preparation and Polish Rear Bumper and other affected Remove and Refit Reverse Sensors to assist repair.	areas.		s	20.0	+	20.00
4	Diagnostic Check and Erase Fault Codes after the repair.			s	80.0	0 \$	80.00
Ť	Diagnostic Check and Engel 1 adit Cocce and the repair						
				KASO	u		
				As	90010068	-	
F				1	> Laus	+-	
1					1 1c	1	
+		TOTAL		<del></del>	4>	5	3,199.34
1		GST 7%	1	07/0	8/2200	s	223.95
1		GRAND TOTAL			1340	\$	3,423.29

Resurvey after repair

MVAG20064454 / VAG Singapore Pte Ltd - HQ ENTRY DATE & TIME: 30/07/2020 16:15 SUBMITTED BY: Ong Min Choor

#### SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver. 3. Information provided must be as truthful and accurate as possible: Any wilful misrepresentation or witholding of material facts may allow insurance companies to

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies

Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid

ACCIDENT STATEMENT

30/07/2020 16:15 Date Of Report

29/07/2020 17:25 Date Of Accident

ALONG BKE (SLE) **Exact Location Of Accident** 

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SKE9660D Vehicle Registration Number

Insured/Policyholder

LEE TENG HAN CHESTER Name Of Registered Owner

SXXXX098A NRIC No

CHESTERLEE9965@GMAIL.COM Email Address

(LOCAL) +65-96608580 Mobile Phone No

OTHERS-96608580 Alternative Phone No

Vehicle Particulars

VOLKSWAGEN Manufacturer

**JETTA 1.4 TSI AT 1623G5** Model

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

COMPREHENSIVE Type Of Coverage

Fleet Policy NO

Policy Number MT/00793233

Cover Note Number

Driver

Name of Driver LEE TENG HAN CHESTER

NRIC No SXXXX098A Date Of Birth 03/10/1987 Occupation **INDOOR** 

Date Of Driving Pass 03/05/2007 **Driving Experience** 13 YEARS AND 2 MONTHS

Gender

Mobile Number (LOCAL) +65-96608580 Fax Number

Contact Number OTHERS-96608580

EMall Address CHESTERLEE9965@GMAIL.COM Address

315B PUNGGOL WAY #17-671

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST, PARKED

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

PUNGGOL N.P.C

ROAD: 21A TEBING LANE, POSTCODE: 828837, COUNTRY:

SINGAPORE

Police Station Address Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ACCIDENT STATEMENT AND POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO FILE TO BIG

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number

SLX9865T

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Page 2 of 24


# ccident Toolkit

## sketch plan

sketch of accident scene:

please illustrate the layout of roads with arrows showing the direction and position of vehicles at the time of impact. Also please note the road names, road signs and vehicle registration numbers.

If safe, please take photos or videos from all angles.




On 24/07/2020 at about 1726 how, I was driving rolong BICE to words SICE in my vehicle bearing the regulation plate SICE 1600 in the third lane. It was driveling and the round surface was not. Due to the heavy traffic ahead of me, I should close my vehicle and almost come to a complete stop when I felt on imped from the near of the vehicle. I would to stop of the side: the round to extense particulars with the other atmer. However the vehicle that hit my car (Hada Shottle) spend off to my right side and continued along BICE towards maddends. Subsequently I review my in air comerce future and cliscowered that the license plate of the vehicle that collided into mine was SIX 7965 T.

Please indicate on vehicle A (your vehicle) and, vehicle B(third party vehicle), the point of impact and area(s) of visible damage with an arrow.



30/07/2010



Vehicle B (SLX 9865T)

direct asia Call us direct
6665 5555
Claims Support 24/7 Hottlin
6532 1818

## IMPORTANT NOTICE

- 1. Please report correctly the details of the acciden to speed up the claims process.
- 2. This form must be completed by the Policyhold, rand/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurar se companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

30/7/2020

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No .:

1002

## > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Singapore NRIC
wner ID:	098A
/ehide No:	SKE9660D
/ehicle to be Exported:	No
ntended Deregistration Date:	10 Aug 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 14 TSI AT 1623G5
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	CAX976164
Chassis No.:	WVWZZZ16ZCM093707
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,820.00
Original Registration Date:	20 Apr 2012
First Registration Date:	20 Apr 2012
Transfer Count:	2
Actual ARF Paid:	\$20,820.00
e est più propresse chi se che che che propresse di company de la company de la company de la company de la company	
PARF Eligibility:	Yés
PARF Eligibility Expiry Date:	19 Apr 2022
PARF Rebate Amount:	\$11,451.00
COCC. ( C. C.	
COE Expiry Date:	19 Apr 2022
COE Category: COE Period(Years):	A - Car (1600cc & below)
QP Paid:	450,001,00
COE Rebate Amount:	\$50,001.00 \$8,458.00
Total Rebate Amount:	\$19,909.00

