

305414587 Our Job Ref No 🗓 ComfortDelGro Engineering Pte Ltd Date 12/08/20 59 Loyang Drive Singapore 508969 Fax: 6546 8156 **FINALIZATION FORM NTUC** Fax: **TAUFIKH** Attn Vehicle Reg No. : SHA2311P 03-Aug-20 Date of Accident The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-NTUC SLD1361M 1. The repair job shall bill to: 2. The finalized amount shall be: \$0.00 Spare Parts after List discount (a) \$0.00 (b) **Labour Charges** \$0.00 **Total for Part-By-Part Repair Cost** Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$1,450.00 Final Lumpsum Repair cost 2 working days. Estimated normal period for repairs: 3. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature OLIVIA W K Name Name 13/8/20 62148316 Tel Date 65468156 Fax For Official Use Only Document Confirm By Attached Item Amount Remarks (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid NO 3. Survey Fees \$7.49 LTA Search Fee 5. Medical Fees (on behalf of driver, if applicable) Överrun Remarks: