

ASS. REC. BY:

REF:

CC4/FCI20008133/ es3

5444

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLV 30430at Workshop m/s Volkswagenof 17, Tux Ave 9Insured: FCC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 68k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLV 30430Yr Regn: 2017, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen SPORTSVAN 1.4c.c 1395Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 67693

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAU ZJW 519090Gen. Cond: Good / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / SRM / STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 01/08/2020Survey held at VolkswagenDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.F. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

v.sg/lt/vrl/action/enquireRebateByPublicBeforeDeregInput?FUNCTION_ID=F030400

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	544H
Vehicle No.:	SLV3093D
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Aug 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SPORTSVAN 1.4 AT AM13HZ CL
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CZC863714
Chassis No.:	WVWZZZAUZJW519090
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$22,344.00
Original Registration Date:	27 Dec 2017
First Registration Date:	27 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$18,282.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Dec 2027
PARF Rebate Amount:	\$13,711.00
COE Expiry Date:	26 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$28,218.00
Total Rebate Amount:	\$41,929.00

The information contained herein is correct as at 06 Aug 2020

OK



Used 2017 Volkswagen Sportsvar



PARE/COE Rebate Enquiry



t.com/used_cars/info.php?ID=897122&DL=1335

Volkswagen Sportsvan 1.4A TSI Comfortline

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$68,800		
Depreciation ?	\$8,100 /yr View models with similar depre	Reg Date	27-Dec-2017 (7yrs 4mths 20days COE left)
Mileage	19,000 km (7.3k /yr)	Manufactured ?	2015
Road Tax ?	\$624 /yr	Transmission	Auto
Dereg Value ?	\$44,706 as of today (change)	OMV ?	\$22,057
COE ?	\$42,339	ARF ?	\$17,880
Engine Cap	1,395 cc	Power	92.0 kW (123 bhp)
Curb Weight ?	1,383 kg	No. of Owners ?	2
Type of Vehicle	Hatchback		

Features

Turbocharger TSI Engine, 200Nm Torque, 7 Speed DSG Gearbox, Bluetmotion Technology, CD Player, SD Card.
View specs of the Volkswagen Golf (2012)

Accessories

17" Alloy Wheels, Auto Side Folding Mirrors, Dual Climatic Aircon, Adjustable And Foldable Rear Seats, Hill Hold Control, Cruise Control.

Di