

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 1/2

Mr
ONG
GIM CHEONG
54 HUME AVENUE
#06-04
Singapore 596231

Document no.
Document date 04-08-2020
Customer no. 5211024505
Customer GST-ID
Dealer 30001
Job order number 2020017600/ 1
Job order date 03-08-2020
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLV3093D	AM13HZ	27-12-2017	WVWZZZAUZJW519090	Sportsvan 1.4CLBMT 92 TSI D7F	67,693

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
510807417M GRU	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Cover For Bumper Primed	1	pcs.	1,175.85	#1	1,175.85	1,258.16
	REAR BUMPER						
5G6807568D 9B9	Rear Diffusor Satin Black	1	pcs.	323.62	#1	323.62	346.27
	SPOILER						
5G9807305E	Bumper	1	pcs.	619.61	#1	619.61	662.98
	REINFORCEMENT						
510807863A	Attachment Strip	1	pcs.	63.92	#1	63.92	68.39
	BUMPER CENTRE BRACKET						
510807393A	Guide Piece	1	pcs.	37.46	#1	37.46	40.08
	TAILLIGHT LOWER BRACKET LH						
510807394A	Guide Piece	1	pcs.	37.46	#1	37.46	40.08
	TAILLIGHT LOWER BRACKET RH						
510807393C	Guide Piece	1	pcs.	37.46	#1	37.46	40.08
	BUMPER SIDE BRACKET LH						
510807394C	Guide Piece	1	pcs.	37.46	#1	37.46	40.08
	BUMPER SIDE BRACKET RH						
WHT005263	POP-RIVET	4	pcs.	1.09	#1	4.36	4.67
	LABOUR	3	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT	3	pcs.	800.00	#1	2,400.00	2,568.00
	Reverse Sensor	1	pcs.	400.00	#1	400.00	428.00
	MS FIRST CAP DIRECT SETTLEMENT						
	DOA: 01/08/2020						
	TP VEH: SHC3229C						
	SURVEY BY:						

Quotation valid till 10-08-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	480.00	7,657.20	7%	569.60	8,137.20	8,706.80

Customer

Service Advisor

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Mr
ONG
GIM CHEONG
54 HUME AVENUE
#06-04
Singapore 596231

Document no.
Document date 04-08-2020
Customer no. 5211024505
Customer GST-ID
Dealer 30001
Job order number 2020017600/ 1
Job order date 03-08-2020
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLV3093D	AM13HZ	27-12-2017	WVWZZZAUZJW519090	Sportsvan 1.4CLBMT 92 TSI D7F	67,693

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hy 90010064

3 days

06/08/2020 @ 1115

Resy before paint