

Prone

SGK
C33/~~SDK~~20008139/R1sf3

ASSIGNMENT

Veh No: SBT 3203H Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: C.C

Colour BLACK A/C: Insured / Std / NI / NA

Sp. Reading 2157 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JT JBARLBZ702197904

Gen. Cond: Good / ~~Fair~~ / Poor / Burnt

Steering: ~~Worder~~ / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Modi: Nil / ~~S/Rim~~ / STD A/Rim or

N/S	O/S	

BS / DIIN / EXNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or .

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/07/2020 D.O.I. 07/08/2020

Survey held at G.H. Storch

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The W/C / Chassis frame / Body Structure affected due to collision

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

11/08/2020

☐: Prel. Report

☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

LEONARD EISEN / I.E.I. (C)

☐: Interview (\$

	Tech. Invs (\$)
--	-----------------

Weekend (S)