

Prone

SGK
C83/~~50~~20008139/R1sf3

ASSIGNMENT

Veh No: SBT 3203H Yr Regn: 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: C.C

Colour BLACK A/C: Insured / Std / NI / NA

Sp. Reading 2157 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JT JBARLBZ702197900

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Unorder~~ / Jammed / Leaked / Burnt or

Brake: Worder / Jammed / Leaked / Burnt or

Modi: Nil / ~~S/Rim~~ / STD A/Rim or

N/S	O/S	

BS / DIUN / EXNOVA / GY / ES / IZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or .

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/07/2020 D.O.I. 07/08/2020

Survey held at G.H. Storch

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The W/C / Chassis frame / Body Structure affected due to collision

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐ : Prelim. Report
☒ : Final Report

Resurvey No. of Trip:

Transportation:

 $S + RS.$

1) Photos

Others

! TOTAL

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

LEADERSHIP SYSTEM / I.B.T. (C)