Our Ref

CC20070367/ SHC 333D /WT/CK(st)

Your Ref:

Date

18-Aug-2020

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr Singapore 508969

CHINA TAIPING INSURANCE CO LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

WITHOUT PREJUDICE

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

COMFORTDELGRO

Mainline +65 6383 6280 Facsimilie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

205 Braddell Road

Singapore 579701 Lovang

59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

**Attn: Motor Claims Department** Dear Sir ACCIDENT INVOLVING OUR TAXI SHC 333D YOUR INSURED SML1688S AND OTHER 2 VEHICLES We are the authorised repair workshop for Citycab Pte Ltd, the owner of motor Vehicle No : SHC 333D which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle. As the accident was caused by the negligent act of your insured driving : SML1688S we are submitting these claims for your consideration on behalf of the claimants. TAXI OWNER'S CLAIM 3,584.50 Cost of Repair 1 344.85 days Loss of Rental @ \$ 114.95 per day 2 (Surveyed by M/s LKK) Survey Report Fees 3 7.49 LTA Search Fees 4 GIA / Police Report Fees 5 Towing / Medical / Transporation Fees 6 Sub Total: 3,936.84 HIRER'S CLAIM \$ 240.00 80.00 per days 3 days Loss of Income @ Total Claims: \$ 4,176.84 We enclose herewith the following documents to support the claims: -Original repair bill: SML1688S LTA search slip/s of : b) **SHC 333D** GIA / Police report/s of : c) Letter of authority from owner / hirer / operator ( ) Certificate of Insurance ) Photocopies of Accident Scene Photos

(x) Downtime/Mileage record

(x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Catherine Koh

**CDGE Claims Department** 

Tel: 6214 8733 Fax: 6214 1843 Email: catherinekoh@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

## LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

i 40 SHC333D , SML1688S , SJZ5186J , ... ON 28-Jul-20 10:30

ALONG

STEVENS ROAD X SCOTTS ROAD

I / We

SYED AZAM BIN SYED ...

(Hirer) NRIC No.:

SXXXX540F

and/or

(Relief) NRIC No.: SXXXX540F

Taxi Number

SHC333D

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

28-Jul-2020

Name of Hirer

**SYED AZAM BIN SYED MOHD** 

Hirer NRIC

SXXXX540F

Signature:

Azam

Address

426D YISHUN AVENUE 11 #04-92

764426

Contact No.

87218665



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 24 Senoko Loop Singapore 758156 7 Sungel Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 76873 320 Ubi Road 3 Sin

COMPANY REG. NO.: 199506048W

Page: 1

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE 079909

CONTACT NO: 62222366

VEHCLE NO SHC 333D

NO/DATE 91518897 12.08.2020

MAKE HYUNDAI JOB NO. 305414815

MODEL I - 40

ODOMETER READING

**DATE OF REG** 17.03.2016

JOB TYPE

CHASSIS CODE KMHLB41UMGU085551

Description: 3P 28.07.2020

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt Add GST @ 7.000

Total Invoice amount

3,584.50

Issued by : Repair Type : Payment Type/Term :

KATHERINETAN 12.08.2020 15:29:06 CFSO/57/57 /Credit 30 days

## ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

Kindly note that no receipt shall be issued unless requested.

**CUSTOMER'S COPY** 

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ N
	Y		
			<u> </u>

Our Ref: CC20070367

Date: 12 August 2020



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

28/07/2020 @ 10:30 hrs

ALONG

STEVENS ROAD X SCOTTS ROAD

INVOLVING

SML1688S, SJZ5186J, SMC4732A

We refer to the above-mentioned accident and wish to inform that CityCab Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC0333D (the "Taxi"). The Taxi was hired to SYED AZAM BIN SYED MOHD IC NO SXXXX540F a registered hirer-operator of CityCab Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$114.95 per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SHC 333D

							And the second second second
DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE	HOURS OPERATED (TIME)			
			(KM)	FROM TO	DATE	NAME OF DRIVER	MILE
2	12CIDEM		5	1015			
28	Kepalir	7	OWO	1-	736	as and a second	
The state of the s			_				
	1.0						To a constant of the constant facility
				3			
				P			

**Enquire Vehicle Insurance Details** 

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SML1688S 28 Jul 2020 / 10:30:00 Successful C01 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

ОК

SMC 3330