

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse  
Singapore 199555

**Our File No:** CS/LPC20008166/KTF3E2

**Date:** 21/08/2020

### REFERENCE

|                   |                                     |                  |                      |
|-------------------|-------------------------------------|------------------|----------------------|
| Insured/Claimant: | COOL AIR-CONDITIONING ENGRG PTE LTD | Policy No:       | Z19VC05003631        |
| Date of Loss:     | 01/08/2020                          | Nature of Claim: | OD                   |
|                   |                                     | Claim No:        | 19/20/20/VC05/023514 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |   |             |                   |
|-----------------------------|---|-------------|-------------------|
| Reg No:                     | GBD4480B  |             |                   |
| Make & Model:               | NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) | Engine No:  | K9KC400D053765    |
| Reg. Date:                  | 21/10/2014 (Man. Year: 2014)                      | Chassis No: | VSKYBAM20Z0088873 |
| Colour:                     | Black   | Odometer:   | 0 km              |
| Engine Capacity:            | 1461 cc   |             |                   |
| Market Value/New Car Price: | S\$27,000.00                                      |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>                 |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                |                  |               |
|-------------------|----------------|------------------|---------------|
| Front Tyre Size:  | 175/70 R14     | Rear Tyre Size:  | 175/70 R14    |
| Front Left Side:  | GREEN-MAX 2 mm | Rear Left Side:  | ALFO MAT 8 mm |
| Front Right Side: | GREEN-MAX 2 mm | Rear Right Side: | Falken 8 mm   |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

|                             |                              |                                     |
|-----------------------------|------------------------------|-------------------------------------|
| Date of Assignment:         | 06/08/2020 Present Location: | K Kim Hin Auto Pte Ltd (HQ)         |
| Date Inspected:             | 07/08/2020 Inspected At:     | K Kim Hin Auto Pte Ltd (HQ)         |
|                             |                              | 160 Sin Ming Drive #02-20, Sin Ming |
|                             |                              | AutoCity                            |
|                             |                              | Singapore 575722                    |
| Estimated Period of Repair: | 0.0 days                     |                                     |

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :           \$27,000.00  
OMV :                   \$20,286.00  
PARF Rebate (1) :       \$   0.00  
Quota Premium Paid :    \$49,901.00  
COE Rebate (2) :        \$20,966.00  
Total Rebate (1) + (2) = : \$20,966.00

The total amount incurred will be Market Value \$27,000.00 minus Total Rebate \$20,966.00 = \$6,034.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 20 Aug 2020)   |  |
| <b>Parts:</b>        | N/A  | NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBD4480B)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

**< END OF ESTIMATES >**