

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305415361
 REGN NO : SH 8772K
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 07.05.2015
 DATE/TIME IN : 06.08.2020 14:10
 ACCIDENT DATE : 05.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER W LIP & FOG LAMP C 1 1,052.20 20.00 841.76 *der*
 0002 04-01-0103-0781-A LAMP ASSY-HEAD LH# 1 1,388.00 20.00 1,110.40 *cnr*

SUB-TOTAL : 1,952.16

JOB NATURE

0000 PB PANEL BEATING 300.00 *280*
 0001 SP SPRAYPAINT CHARGE 300.00 *200*
 0002 17-01 CHECK ALL LIGHTING 50.00 *30*

SUB-TOTAL : 650.00

TOTAL : 2,602.16 *1952.16*

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE: *6/8/2020*

DATE:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495744
'wp'
02 days
Resurvey after repair
tanpin@lkhaut.com
6/8/20 @ 5pm
Hankook

2 days