

WIG (LIS)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 06.08.2020

Time: 15:50:41

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305415361
REGN NO : SH 8772K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 07.05.2015
DATE/TIME IN : 06.08.2020 14:10
ACCIDENT DATE : 05.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER W LIP & FOG LAMP C 1 1,052.20 20.00 841.76 *de*
0002 04-01-0103-0781-A LAMP ASSY-HEAD LH# 1 1,388.00 20.00 1,110.40 *one*

SUB-TOTAL : 1,952.16

JOB NATURE

0000 PB PANEL BEATING 300.00 *280*
0001 SP SPRAYPAINT CHARGE 300.00 *200*
0002 17-01 CHECK ALL LIGHTING 50.00 *30*

SUB-TOTAL : 650.00

TOTAL : 2,602.16

Tumani
MVA NAME & SIGNATURE
DATE: *6/8/2020*

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

Tanpin 17495744
'wp'
6/8/2020 02 days
Resurvey after repair
tanpin@lkhaut.com
6/8/20 @ 5pm
Hankook

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: