



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL Ref : CS3/SMO20003725/Gvf3e2-1

50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWERSINGAPORE 048623

Date : 17-08-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 3323U	Veh. Inspected	SJX 7459U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2001014/THE	Excess (\$)	0.00
Assign From	THELMA CHOO	Assign Date	07/08/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11105067	Colour	WHITE
Odometer	118894	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	CST	6 mm
L/H Front Tyre	215/60 R16	CST	6 mm
R/H Rear Tyre	215/60 R16	CONTINENTAL	5 mm
L/H Rear Tyre	215/60 R16	CONTINENTAL	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/03/2020	Inspection Date	09/03/2020
Survey held at	THE MECHANIC PTE LTD 8 KAKI BUKIT AVENUE 4 #02-46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**