

ASS. REC. BY:

Steve

REF:

CS3/A1620008178/ESf3

ASSIGNMENT

PRS

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMJ 2033K

Yr Regn:

26/2/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

c.c.

1591

Colour

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

White

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHD841CMK4866930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

11/8/20

D.O.I.

11/8/20

Survey held at

Sin Wee Chuan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-68K

Date/Time, File Pass to?

13/08/2020

1) TYPIST

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Rep. Format:

PRS

Lump Sum / L.B.I. (%)

(1) Bent (2) Damaged (3) Distorted (4) Cracked (5) Bent (6) Blended (7) Flashed (8) Stained
(9) Shaded (10) Blended (11) Broken (12) Necessary (13) Missing (14) Tom
(15) Unfinished (16) Not Working

MOTOR CAR (Prt)

AS 0901661

Aug 1995

(1) Pallet (2) 1 (3) Pallet (4) 1 (5) Pallet (6) 1

(7) Pallet (8) 1 (9) Pallet (10) 1

SMT 2033K

Front Portion

Vehicle No.

NAC	INC	Item	CON	AC	Qty
1001	991886	Fit Number Plate	CUT	✓	
1002	991887	Fit Number Plate Base			
1003	991889	Fit Number Plate Garnish	CUT	✓	
1004	991900	Fit Bumper	DEC	✓	
1005	992341	Fit Bumper Clips	DEC	✓	
1006	991325	Fit Bumper Bracket	DEC	✓	
1007	991462	Fit Bumper Side Retainer	BR	✓	2
1008	991433	Fit Bumper Reinforcement			
1009	991318	Fit Bumper Beam			
1010	991468	Fit Bumper Sponge			
1011	991427	Fit Bumper Protector			
1012	991420	Fit Bumper End Tow Eye Cover	CUT	✓	
1013	991363	Fit Bumper Grille			
1014	991301	Fit Bumper Moulding			
1015	991407	Fit Bumper Lower Spoiler			
1016	991438	Fit Bumper Sensor			
1017	995100	Fit LH Bumper Fog Lamp Cover			
1018	991355	Fit RH Bumper Fog Lamp Cover			
1019	995079	Fit LH Bumper Fog Lamp			
1020	995080	Fit RH Bumper Fog Lamp			
1021	991793	Fit Grille	CUT	✓	
1022	991328	Fit Grille Emblem	NEC	✓	
1023	991799	Fit Grille Chrome Moulding			
1024	991222	Fit Apron Panel			
1025	992013	Fit Support Panel			
1026	992025	Fit Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Fit Brace Panel			
1029	995153	Fit LH Headlamp Assy			
1030	991821	Fit RH Headlamp Assy	CUT	✓	
1031	995088	Fit LH Side Lamp			
1032	995089	Fit RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990705	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990689	Air Cleaner Resonator			
1063	991712	Fit Exhaust Manifold			
1064	991713	Fit Exhaust Manifold Cover			
1065	991054	Fit Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Pelley Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Fit			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Pin			
1091	992234	Gear Box Mounting			
1092	991520	Fit LH Chassis Member			
1093	991520	Fit RH Chassis Member			
1094	990728	Fit Vertical Cross Member			
1095	991863	Fit Lower Cross Member			
1096	995070	Fit LH Fender			
1097	995072	Fit LH Fender Inner Panel			
1098	995147	Fit LH Fender Lamp			
1099	995148	Fit LH Fender Protector			
1100	991740	Fit LH Fender Inner Shield			
1101	995179	Fit LH Mudflap			
1102	995170	Fit LH Wheel Rim			
1103	994025	Fit LH Rim Cover			
1104	995065	Fit LH Tyre			
1105	995071	Fit RH Fender			
1106	991739	Fit RH Fender Inner Panel			
1107	991744	Fit RH Fender Lamp			
1108	991752	Fit RH Fender Protector			
1109	991740	Fit RH Fender Inner Shield			
1110	991884	Fit RH Mudflap			
1111	992087	Fit RH Wheel Rim			
1112	994025	Fit RH Rim Cover			
1113	995065	Fit RH Tyre			
1114	992093	Fit Windscreen Glass			
1115	992117	Fit Windscreen Rubber			
1116	992108	Fit Windscreen Moulding			
1117	992093	Fit Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Fit Wiper Arm			
1121	992142	Fit Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Fit Driver Seat			
1133	991922	Fit RH Seat Belt Assy			
1134	991899	Fit Passenger Seat			
1135	995182	Fit LH Seat Belt Assy			
1136	990247	Sticker			

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/08/2020 10:31
Date Of Accident 01/08/2020 11:40
Exact Location Of Accident CHANGI ROAD OUTSIDE SING LIAN BUILDING
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ2033K
Insured/Policyholder
Name Of Registered Owner TEO JEE TONG
NRIC No SXXXX208G
Email Address DTEOAK@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-96604609
Alternative Phone No OTHERS-96604609

Vehicle Particulars

Manufacturer HYUNDAI
Model AD AVANTE 1.6 GLS (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number VPAP2379671
Cover Note Number

Driver

Name of Driver TEO JEE TONG
NRIC No SXXXX208G
Date Of Birth 10/04/1965
Occupation OUTDOOR
Date Of Driving Pass 02/03/1987
Driving Experience 33 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96604609
Fax Number
Contact Number OTHERS-96604609
Email Address DTEOAK@HOTMAIL.COM

Address	APT BLK 842B TAMPINES STREET 82 #16-30
Postcode	522842
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY KAREN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	THE VIDEO WAS OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM4625K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/8/2020 at Changi Road, I was come out from Sing Lion Bulding and I was stopping at Junction to check traffic. After I check the traffic, I wanted go to straight and suddenly, vehicle B come at my right side. Then vehicle B collided onto my vehicle. After accident, I made a check and I saw my vehicle have damaged at my right side of vehicle. We exchange particular and we left the scene.

I wish state that during accident, vehicle B didn't have slow down when I was wanted go to straight.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: