COMFORTDELGRO ENGINEERING

Our Ref : __3054l5363__

Date : __07.08.2020__

Time of Fax : _____

__ATG.__

Via Fax : __EMAIL__

Your Insured : __YP 6520X__

Date of Acc : __06.08.2020__

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimilie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Defu
6 Defu Avenue 1
Singapore 539537

Marymount
600 Sin Ming Avenue
Singapore 575733

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO __SMD 3027 M__

1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.

2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

3 Enclosed, please find :

I) Our initial estimate of repairs of the damaged vehicle.
II) Accident report made by our client.

4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng	Tel no. 62148316 or Hp no. 98240811
Jumari Masudin	Tel no. 62148315 or Hp no. 96355305
Chiang Liat Choon	Tel no. 62148314
Lim Tien Siong	Tel no. 62148398 or Hp no. 96358546

5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.

6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully

for Vice President
Crash Repairs & Claims Recovery

A member of

COMFORTDELGRO

SINGAPORE
QUALITY CLASS

SGS

ISO 9000
PSB
CERT. NO.: 95-2-0518
SS ISO 9001 : 2000