

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3027M

MAKE :

MODEL I-40

AIG

LKK/Chang,
06/08/2020

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	BOOT LID			\$2,174.90
1	BOOT HINGE /RH			\$142.30
1	BOOT LID H EMBLEM			\$28.70
1	BOOT LID CRDI PLATE			\$27.90
1	BOOT LID I 40			\$27.90
1	BOOT LID LAMP /RH			\$565.60
1	TAIL LAMP /RH			\$697.80
1	REAR BUMPER			\$1,106.00
	SUB TOTAL			\$4,771.10
	20.00%			\$954.40
				\$3,817.60
1	REAR NUMBER PLATE			X \$55.00
1	BOOTLID COMFORT LOGO STICKER			\$30.00
1	BOOTLD COMFORT TEL NO. STICKER			\$30.00
				\$115.00
	Labour Charge			
	Panel Beating			\$540.00
	Spray Painting Charge			\$640.00
	Towing Fee			\$60.00
	Tuff Kote			\$90.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,390.00
	ESTIMATE TOTAL			\$5,322.60
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Taufik 97475749
 WP' 7/8/20 4pm
 02-03 days
 Repair after survey
 Taufik Consultants
 Hkndch.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 07.08.2020 09:18

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.: 305415363

CUSTOMER
COMFORT TRANSPORTATION PTE LTD
7010045
CUSTOMER NO.
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755
(R) (O)
(P)


COUNT CARD NO.

REGN NO:	SHD3027M	MILEAGE
MAKE:	HYUNDAI	FUEL E.....1/2.....F
MODEL	I-40	DATE/TIME IN 06.08.2020 14:30
YR OF MANU	07.04.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU086948	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 06.08.2020
NATURE: 3P 06.08.2020

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHD3027M

CHIANG

Vehicle No.: SHD3027M

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection