



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19006235/Esf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 21-08-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7631H	Veh. Inspected	SKG 4215D
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19040231	Excess (\$)	0.00
Assign From	CARINE KEK	Assign Date	07/08/2020

2. Vehicle Particulars & Condition

Make & Model	VOLVO S60	c.c	1596
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	YV1FS48HBC2143615	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R17	GOODYEAR	6 mm
L/H Front Tyre	215/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	215/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	215/50 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND INTERIOR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/04/2019	Inspection Date	10/04/2019
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
-------------------------------------	-----------------