



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20008191/Ksf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 16-09-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GY 4490C	Veh. Inspected	SJU 1253B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002308/SYH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	07/08/2020

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET CRUZE (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KL1JA6961AK564518	Colour	WHITE
Odometer	131352	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	GENERAL	6 mm
L/H Front Tyre	215/55 R17	GENERAL	6 mm
R/H Rear Tyre	215/55 R17	GENERAL	8 mm
L/H Rear Tyre	215/55 R17	GENERAL	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/08/2020	Inspection Date	11/08/2020
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------