

ASS. REC. BY:

REF: CS/CTI20008215/Gtf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTI Date/Time: 7/8/2020 5:21 PM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFU1031Y Insured: GBJ 7879J

at Workshop m/s Ah Lim Motor Company Tel: 64831244

of 10 Ang Mo Kio Ind Pk 2A #01-09 AMK AUTOPOINT

Policy No: DMCVSN30652919000 Claim No: SNM20D202765

Sum Insured: Excess:

Make of Veh: D.O.A. 06/08/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 11-8-20 9.17A.M Person Contacted: ZILA Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SFU 1031Y- CC6/AXA15006436/Kua3s2 DOA :11/04/2015
	GBJ 7879J- X