



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/LAW20008225/Atf3s2

C/O COMLAW LLC
64 CECIL ST #06-01 IOB BLDGSINGAPORE 049711

Date : 22-09-2020



Code : INC3

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SHC 6962Z	Veh. Inspected	SMA 8060P
Policy No.	5095103893	Coverage (\$)	0.00
Claim No.	DV.2020.220697.ntuc	Excess (\$)	0.00
Assign From	BIJIAO	Assign Date	07/08/2020

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET CRUZE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KL1JA6961AK549258	Colour	GREY
Odometer	152613	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	DUNLOP	6 mm
L/H Front Tyre	225/45 R17	DUNLOP	6 mm
R/H Rear Tyre	225/45 R17	DUNLOP	6 mm
L/H Rear Tyre	225/45 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

5. General Information

Accident Date	10/09/2018	Inspection Date	19/08/2020
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------