

ASS. REC. BY:

REF: CS/CTI20008271/Kvf3

Special Instruction:

Surveyor: KENNETH

ASSIGNMENT (Office)

From (Person): BEN TANG of CTI Date/Time: 11/8/2020 4:20 PM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 3658G Insured: PC 7725R

at Workshop m/s S Three Automotive Recovery Pte Ltd Tel: 62841542/6284 1575

of Blk 8 Sin Ming Industrial Estate #01-64/66

Policy No: Claim No: SNM20D202770

Sum Insured: Excess:

Make of Veh: D.O.A. 07.08.20  
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11-8-20 4.24P.M Person Contacted: YAN Vehicle ☒ IN / OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | SKW 3658G- CS/AIG19016719/Kvf3n2 DOA :14/09/2019                    |
|           | PC 7725R- X                                                         |
| 13/8/20   | Email preli revised to Ben                                          |
| 8/9/20    | LS \$5800 confirmed (Red 10,636.99, 65%)                            |