

ASS. REC. BY:

P. J. ...

REF:

CC3/AK2000827 | es3

597X

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 5300B

at Workshop m/s PERFORMANCE

of 303, ALEXANDRA RD

Insured: AIG

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 63K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKR 5300B Yr Regn: 2015 1PEB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 218 I A.T c.c 1499

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 36059 T/Radlo: Insured / Std / NI / NA

Eng/No: _____

C/No: WDA 2A 32000VZ 50802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/08/2020 D.O.I. 31/08/2020

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL _____

Rep. Format: _____

Lump Sum / I.B.A. (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Foreign Identification Number
Owner ID:	597X
Vehicle No.:	SKR5300B
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Aug 2020
Vehicle Make:	B.M.W.
Vehicle Model:	218I ACTIVE TOURER D/AB LED DSC ABS NAV
Primary Colour:	Brown
Manufacturing Year:	2014
Engine No.:	F2660983838A15A
Chassis No.:	WBA2A32000VZ50802
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$26,690.00
Original Registration Date:	13 Feb 2015
First Registration Date:	13 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$19,366.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Feb 2025
PARF Rebate Amount:	\$13,556.00
Intended COE Rebate Details	
COE Expiry Date:	12 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$70,890.00
COE Rebate Amount:	\$31,562.00
Total Rebate Amount:	\$45,118.00

The information contained herein is correct as at 31 Aug 2020

OK

Brown



Merimen e-Claims



Used 2015 BMW 2 Series 218i Active Tourer

PARF/COE

mart.com/used_cars/info.php?ID=913840&DL=2563

▶ BMW 2 Series 218i Active Tourer

Overview

Financial

Accessories

Similar

Research

Photos

Map

RENTCARLEASE PTE LTD in affiliation with



COMPLETE CAR TRADE SOLUTIONS

Price	\$62,800		
Depreciation ⓘ	\$11,420 /yr View models with similar depre	Reg Date	08-Jan-2015 (4yrs 4mths 7days COE left)
Mileage	45,000 km (8k /yr)	Manufactured ⓘ	2014
Road Tax ⓘ	\$684 /yr	Transmission	Auto
Dereg Value ⓘ	\$51,064 as of today (change)	OMV ⓘ	\$31,497
COE ⓘ	\$75,289	ARF ⓘ	\$26,096
Engine Cap	1,499 cc	Power	100.0 kW (134 bhp)
Curb Weight ⓘ	1,360 kg	No. of Owners ⓘ	2
Type of Vehicle	Hatchback		

Features

1.5L 3 Cylinder Inline 12 Valve TwinPower Turbocharged. 134 Bhp Of Power. 220 Nm Of Torque. 6 Speed Transmission, 0-100Km/H In 9.2sec. View specs of the BMW 2 Series Active Tourer (2014)

